

HISTORICAL  
RECORDS

S/N

8424183

ULLS-A E  
GENERATED

1. AIRCRAFT MODEL <b>CH-47D</b>	2. NOMENCLATURE <b>HELICOPTER, CARGO</b>	3. AIRCRAFT SERIAL NUMBER <b>8424183</b>		
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID
ACFT S/N 70-15019, CH47C, INDUCTED AND CONVERTED TO CH47D, S/N 84-24183 ON 21-AUG-1985. TOTAL TIME AT MODIFICATION 1868.2 HRS. (RH7244)	BOEING VERTOL, PHILA, PA	10-Oct-1985	1	QC000000
INSTALLATION AT BOEING VERTOL FACILITY OF ENGINEERING CHANGE PROPOSAL (ECP) PHL-CH47D-035, INTERIM NIGHT VISION GOGGLE COMPATIBLE COCKPIT HAS BEEN COMPLIED ON THIS ACFT.ECP KIT 145EK350. (RH7244)	BOEING VERTOL, PHILA, PA	10-Oct-1985	2	QC000000
ACFT INSPECTION CHECKLIST SYSTEM CONVERTED TO THE PROGRESSIVE PREVENTIVE MAINTENANCE (PPM) INSP PROCEDURES IN ACCORDANCE WITH TM 55-1520-240-PPM. THIS TM WILL BE APPLIED IN LIEU OF TM 55-1520-240-PMS AND TM 55-1520-240-PM. TOTAL TIME ON ACFT 1868.2 HRS. (RH7244)	BOEING VERTOL, PHILA, PA	10-Oct-1985	3	QC000000
TB 55-1520-241-20-28 INSTALLATION OF CH47D STAINLESS STEEL FLIGHT CONTROL TUBES COMPLIED WITH. (RH7244)	BOEING VERTOL, PHILA, PA	10-Oct-1985	4	QC000000
SOF MSG CH47-85-07 ONE TIME INSPECTION OF PITCH LINK CONNECTING BOLTS. P/N 114R3650-13 COMPLIED WITH (TB 55-1520-241-20-32). (RH7244)	BOEING VERTOL, PHILA, PA	10-Oct-1985	5	QC000000
ACFT S/N 84-24183 TEST FLOWN AND ACCEPTED AT 1876.8 HRS. (RH7244)	BOEING VERTOL, PHILA, PA	05-Nov-1985	1	QC000000
INSPECT FWD AND AFT ROTOR HEAD VERTICAL HINGE PINS I/A/W TB 55-1520-241-20-35 (SOF MSG CH-47-85-19) COMPLIED WITH AT 1885.8 ACFT BY B CO 159TH AVN BN, FTCKY. (RH7244)	B CO 159TH AVN BN, FTCKY	20-Nov-1985	1	QC000000
INSPECTION: FLT CONTROL MOUNTING PALLETS I/A/W TB 55-1520-240-20-10 (SOF MSG CH-47-85-21) COMPLETED AT 1898.2 ACFT HRS BY B CO 159TH AVN BN. (RH7244)	B CO 159TH AVN BN, FTCKY	12-Dec-1985	1	QC000000
SOF MSG CH-47-86-01 TB 55-1520-241-20-37 ONE TIME INSPECTION OF P/C/L UPPER BOLTS COMPLIED WITH AT 1952.1 ACFT IRS. (RH7244)	B CO 159TH AVN BN, FTCKY	11-Apr-1986	1	QC000000

1. AIRCRAFT MODEL <b>CH-47D</b>	2. NOMENCLATURE <b>HELICOPTER, CARGO</b>	3. AIRCRAFT SERIAL NUMBER <b>8424183</b>		
REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID
OCM/ACE PERFORMED AT 2004.0 ACFT HRS AT FTCKY BY ACE TEAM MEMBER "P" AVSOM OCMSEC, ST LOUIS, MO. (RH7244)	AVSOM OCMSEC, FTCKY	01-Jul-1986	1	QC000000
ONE TIME INSPECTION OF CH47D FLOORS AND STRUCTURES C/W TB 55-1520-241-20-38. (RH7244)	B CO 159TH AVN BN, FTCKY	01-Jul-1986	2	QC000000
ONE TIME INSPECTION OF FWD AND AFT LCT ACTUATORS COMPLIED WITH I/A/W SOF MSG CH-47-86-06 TB 55-1520-240-20-11. (RH7244)	B CO 159TH AVN BN, FTCKY	08-Jul-1986	1	QC000000
ONE TIME INSPECTION OF CH47D MANUAL RELEASE CABLE TO FWD HOOK C/W T/A/W TB 55-1520-241-20-39. (RH7244)	B CO 159TH AVN BN, FTCKY	13-Aug-1986	1	QC000000
ONE TIME INSPECTION OF CH47 SERIES ACFT REVISION TO CORROSION REQUIREMENTS C/W I/A/W SOF MSG CH-47-86-08 TB 55-1520-241-20-38. REQUIREMENTS C/W I/A/W SOF MSG CH-47-86-08 TB 55-1520-241-20-38. (RH7244)	B CO 159TH AVN BN, FTCKY	15-Oct-1986	1	QC000000
ONE TIME INSPECTION OF CH47D XMSN PRESSURE SWITCHES C/W I/A/W SOF MSG CH-47-86-09. (RH7244)	B CO 159TH AVN BN, FTCKY	23-Oct-1986	1	QC000000
ONE TIME INSPECTION OF #1 AND #2 ENGINE XMSN BREATHER LINES C/W I/A/W SOF MSG CH-47-86-10 TB 55-1520-241-20-40. (RH7244)	B CO 159TH AVN BN, FTCKY	14-Nov-1986	1	QC000000
ONE TIME INSPECTION OF FWD AND AFT ROTOR HEADS WITH ON 145R2003-1 AND 145R2004-2 I/A/W SOF MSG CH-47-87-01. (RH7244)	B CO 159TH AVN BN, FTCKY	14-Jan-1987	1	QC000000
ONE TIME AND RECURRING INSPECTION OF CH47A,B,C,D ACFT ENGINE CROSS SHAFT C/W I/A/W SOF MSG CH-47-87-02 TB 55-1520-241-20-42. (RH7244)	B CO 159TH AVN BN, FTCKY	01-Feb-1987	1	QC000000
ONE TIME INSPECTION OF CH47D HELICOPTER PIVOTING AND SWIVELING ACTUATOR LOWER STRUCTURAL CONNECTON FOR PROPER HARDWARE C/W I/A/W SOF MSG CH-47-87-03 TB 55-1520-240-20-13. (RH7244)	B CO 159TH AVN BN, FTCKY	11-Feb-1987	1	QC000000

1. AIRCRAFT MODEL <b>CH-47D</b>	2. NOMENCLATURE <b>HELICOPTER, CARGO</b>	3. AIRCRAFT SERIAL NUMBER <b>8424183</b>		
REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID
ONE TIME INSPECTION OF CH47D AFT XMSN COOLER FAN QUILL SHAFT C/W I/A/W SOF MSG CH-47-87-04 TB 55-1520-240-20-14 AT 2199.8 ACFT HRS. (RH7244)	B CO 159TH AVN BN, FTCKY	10-Mar-1987	1	QC000000
PPM #30 CYCLE 1 COMPLETED 29-FEB-1987 AT 2166.7 ACFT HRS BY B CO. (RH7244)	B CO 159TH AVN BN, FTCKY	27-Mar-1987	1	QC000000
ONE TIME INSPECTION OF ALL TIME CHANGE COMPONENTS/PARTS HISTORICAL RECORDS TO IDENTIFY NON-CONFORMING PART/PARTS I/A/W SOF MSG GEN-87-03 TB 55-1500-200-20-25 C/W AT 2265.7 ACFT HRS. (RH7244)	B CO 159TH AVN BN, FTCKY	05-Jul-1987	1	QC000000
ONE TIME INSPECTION OF CH47 ENGINE CROSS SHAFT BOLTS (REPLACEMENT) C/W I/A/W SOF MSG CH-47-87-06 MWO 55-1520-240-22-2 AT 2277.0 ACFT HRS. (RH7244)	B CO 159TH AVN BN, FTCKY	10-Jul-1987	1	QC000000
ONE TIME INSPECTION OF SHAFT COUPLING WASHERS COMPLIED WITH I/A/W SOF MSG CH-47-87-10 TB 55-1520-241-20-45 AT 2334.2 ACFT HRS. (RH7244)	B CO 159TH AVN BN, FTCKY	16-Sep-1987	1	QC000000
ONE TIME INSPECTION OF C-BOX FAN DRIVE SHAFT COMPLIED WITH I/A/W SOF MSG CH-47-87-11 TB 55-1520-240-20-16 AT 2346.0 ACFT HRS. (RH7244)	B CO 159TH AVN BN, FTCKY	25-Sep-1987	1	QC000000
ONE TIME INSPECTION OF FUEL FLOW TRANSMITTER C/W I/A/W SOF MSG CH-47-87-13 TB 55-1520-240-20-18 AT 2421.9 ACFT HRS. (RH7244)	B CO 7/101 AVN REGT, FTCKY	16-Nov-1987	1	QC000000
OCM/ACE PERFORMED AT 2440.0 ACFT HRS AT FTCKY. (RH7244)	AVSCOM OCMSEC, FTCKY	24-Nov-1987	1	QC000000
ONE TIME INSPECTION OF FLIGHT CONTROL AND UTILITY HYDRAULIC PUMP HOUSING RETAINING SCREWS C/W I/A/W SOF MSG CH-47-87-14 TB 55-1520-240-20-19 AT 2439.5 ACFT HRS. (RH7244)	B CO 7/101 AVN REGT, FTCKY	20-Jan-1988	1	QC000000

1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO	3. AIRCRAFT SERIAL NUMBER 8424183		
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID
ONE TIME INSPECTION OF HEATER FUEL LINE AND ELECTRICAL WIRE BUNDLES FROM STA 105 TO STA 380 C/W I/A/W SOF MSG CH-47-88-03 TB 55-1520-240-20-20 AT 2450.7 ACFT HRS. (RH7244)	B CO 7/101 AVN REGT, FTCKY	07-Mar-1988	1	QC000000
ONE TIME INSPECTION OF DRIVE SHAFT ASSY C/W I/A/W SOF MSG CH-47-88-07 TB 55 1520-240-20-21 AT 2466.0 ACFT HRS. (RH7244)	B CO 7/101 AVN REGT, FTCKY	23-Mar-1988	1	QC000000
ONE TIME AND RECURRING INSPECTION OF FLIGHT CONTROLS AND UTILITY HYD PUMP HOUSING RETAINING SCREWS C/W I/A/W SOF MSG CH-47-88-10 TB55-1520-240-19 AT 2493.7 ACFT HRS. (RH7244)	B CO 7/101 AVN REGT, FTCKY	09-Jun-1988	1	QC000000
ONE TIME INSPECTION OF PIVOTING AND SWIVELING SERVOCYLINDERS C/W I/A/W SOF MSG CH-47-88-11 TB 55-1520-240-20-24 AT 2495.2 ACFT HRS. (RH7244)	B CO 7/101 AVN REGT, FTCKY	13-Jun-1988	1	QC000000
ONE TIME INSPECTION OF COMBING XMSN FAN ASSY AND RETORQUE AFT AND COMBING XMSN FAN ASSY I/A/W SOF MSG CH-47-88-12 TB 55-1520-240-20-25 AT 2514.3 ACFT HRS. (RH7244)	B CO 7/101 AVN REGT, FTCKY	23-Jun-1988	1	QC000000
ONE TIME INSPECTION OF COMBING XMSN FAN ASSY C/W I/A/W SOF MSG CH-47-88-13 TB 55-1520-240-50-01 AT 2528.0 ACFT HRS. (RH7244)	B CO 7/101 AVN REGT, FTCKY	06-Jul-1988	1	QC000000
ONE TIME INSPECTION OF PIVOTING AND SWIVELING SERVOCYLINDERS, EXPANDED COVERAGE C/W I/A/W SOF MSG CH-47-88-14 TB 55-1520-240-20-26 AT 2559.1 ACFT HRS. (RH7244)	B CO 7/101 AVN REGT, FTCKY	23-Jul-1988	1	QC000000
INSPECTION OF INTERNAL FUEL TANKS C/W I/A/W SOF MSG CH-47-88-15 TB 55-1520-241-20-48 AT 2663.0 ACFT HRS. (RH7244)	B CO 7/101 AVN REGT, FTCKY	26-Oct-1988	1	QC000000
ONE TIME INSPECTION OF CROSS SHAFT C/W I/A/W SOF MSG CH-47-88-18 TB 55-1520-240-20-28 AT 2708.4 ACFT HRS. (RH7244)	B CO 7/101 AVN REGT, FTCKY	18-Nov-1988	1	QC000000
ERROR	B CO 7/101 AVN REGT, FTCKY	08-Dec-1988	1	QC000000

1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO	3. AIRCRAFT SERIAL NUMBER 8424183			
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID	
OCM/ACE PERFORMED AT 2716.0 ACFT HRS FTCKY BY ACE TEAM MEMBER "B" AVSCOM OCMSEC, ST LOUIS, MO. (RH7244)	B CO 7/101 AVN REGT, FTCKY	08-Dec-1988	2	QC000000	
ERROR	B CO 7/101 AVN REGT, FTCKY	13-Dec-1988	1	QC000000	
ERROR	B CO 7/101 AVN REGT, FTCKY	13-Dec-1988	2	QC000000	
ACFT GROUNDED I/A/W SOF MSG CH-47-88-20 UNTIL RELEASED BY AVSCOM IN FURTHER SOF MSG. (RH7244)	B CO 7/101 AVN REGT, FTCKY	13-Dec-1988	3	QC000000	
SOF MSG GEN-88-02 C/W THIS DATE. (RH7244)	B CO 7/101 AVN REGT, FTCKY	13-Dec-1988	4	QC000000	
ERROR	B CO 7/101 AVN REGT, FTCKY	14-Dec-1988	1	QC000000	
ONE TIME INSPECTION OF ALL CH-47 ACFT C/E I/A/W SOF MSG CH-47-88-21 TB 55-1520-241-20-49 AT 2715.9 ACFT HRS. (RH7244)	B CO 7/101 AVN REGT, FTCKY	14-Dec-1988	2	QC000000	
ERROR	B CO 7/101 AVN REGT, FTCKY	28-Dec-1988	1	QC000000	
ONE TIME INSPECTION OF FWD XMSN COOLER IMPELLER RETAINING NUT AND RETORQUE I/A/W SOF MSG CH-47-88-19 SUPERSEDED BY SOF MSG CH-47-88-23 TB 55-1520-240-20-30. (RH7244)	B CO 7/101 AVN REGT, FTCKY	28-Dec-1988	2	QC000000	
ERROR	B CO 7/101 AVN REGT, FTCKY	29-Dec-1988	1	QC000000	
ONE TIME INSPECTION OF FWD AND AFT XMSN C/W I/A/W SOF MSG CH-47-88-22 TB 55-1520-240-20-29 AT 2715.9 ACFT HRS. (RH7244)	B CO 7/101 AVN REGT, FTCKY	29-Dec-1988	2	QC000000	
ERROR	B CO 7/101 AVN REGT, FTCKY	09-Jan-1989	1	QC000000	
SOF MSG CH-47-89-01 TB 55-1520-240-20-31 INSTRUCTION FOR CONVERSION FROM PPM TO PM RECEIVED: ENTERED ON 2408.13. (RH7244)	B CO 7/101 AVN REGT, FTCKY	09-Jan-1989	2	QC000000	

1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO	3. AIRCRAFT SERIAL NUMBER 8424183		
REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID
ACFT PMD INSPECTION IMPLEMENTED AT 2726.9 ACFT HRS. (RH7244)	B CO 7/101 AVN REGT, FTCKY	18-Jan-1989	1	QC000000
ONE TIME INSPECTION OF FWD XMSN COOLER, IMPELLER RETAINING NUT AND RETORQUE C/W I/A/W SOF MSG CH-47-88-23 TB 55-1520-240-20-30 AT 2728.9 ACFT HRS. (RH7244)	B CO 7/101 AVN REGT, FTCKY	19-Jan-1989	1	QC000000
MWO 55-1520-240-50-38 INTERIM IMPROVEMENT OF HEAT RESIST CAPABILITY FOR FLIGHT CONTROL SYSTEM BELLCRANK, IDLERS AND CONNECTING LINKS C/W BY AVSCOM PROJECT OLR. (RH7244)	B CO 7/101 AVN REGT, FTCKY	09-Feb-1989	1	QC000000
SOF MSG CH-47-89-03 GROUNDING FOR APPLICATION OF MWO 55-1520-240-50-38 C/W BY AVSCOM PROJECT OLR. (RH7244)	B CO 7/101 AVN REGT, FTCKY	09-Feb-1989	2	QC000000
ONE TIME INSPECTION OF FWD AND AFT ROTOR HEAD C/W I/A/W SOF MSG CH-47-89-04 TB 55-1520-240-20-34 AT 2727.9 ACFT HRS. (RH7244)	B CO 7/101 AVN REGT, FTCKY	09-Feb-1989	3	QC000000
SOF MSG CH-47-89-05 TB 55-1520-240-20-35 ONE TIME AND RECURRING INSPECTION OF ALL FLIGHT CONTROL COMPONENTS WITH ALBI PAINT AND PROTECTIVE SLEEVES TO BE INSPECTED N/L/T 2778.6 AFCT HRS OR 29-APR-1989. COMPLETED 2748.6 ACFT HRS. 12-APR-1989. (RH7244)	B CO 7/101 AVN REGT, FTCKY	12-Apr-1989	1	QC000000
ACFT INDUCTED TO PHASE MAINTENANCE AT 2748.6 ACFT HRS. PHASE 1 THRU 4 PREFORMED. NEXT PHASE (1-1) DUE AT 2948.6 AFCT HRS. (RH7244)	B CO 7/101 AVN REGT, FTCKY	24-May-1989	1	QC000000
SOF MSG CH-47-89-06 TB 55-1520-240-20-36: CHANGE INSPECTION INTERVAL FOR ENGINE CROSS SHAFT. C/W 2754.7 ACFT HRS. (RH7244)	B CO 7/101 AVN REGT, FTCKY	23-Jun-1989	1	QC000000
SOF MSG CH-47-89-07 TB 55-1520-240-30-37 ONE TIME INSPECTION OF ILCA RIDGID LINK JAM NUTS. C/W THIS DATE 2781.8 AFCT HRS. (RH7244)	B CO 7/101 AVN REGT, FTCKY	27-Jul-1989	1	QC000000

1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO	3. AIRCRAFT SERIAL NUMBER 8424183		
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID
GROUNDING OF ACFT C/W I/A/W SOF MSG CH-47-89-08 TB 55-1520-240-20-38 AT 2783.1 AFCT HRS. (RH7244)	B CO 7/101 AVN REGT, FTCKY	01-Aug-1989	1	QC000000
GROUNDING OF ACFT C/W I/A/W SOF MSG CH-47-89-09 TB 55-1520-240-20-38 AT 2783.1 AFCT HRS. (RH7244)	B CO 7/101 AVN REGT, FTCKY	11-Aug-1989	1	QC000000
UNGROUNDING REQUIREMENTS FOR CH47D C/W I/A/W SOF MSG CH-47-89-11 TB 55 1520-240-20-40 AT 2783.1 ACFT HRS. (RH7244)	B CO 7/101 AVN REGT, FTCKY	27-Oct-1989	1	QC000000
GROUNDING OF ACFT C/W I/A/W SOF MSG CH-47-89-12 AT 2783.1 ACFT HRS. (RH7244)	B CO 7/101 AVN REGT, FTCKY	30-Oct-1989	1	QC000000
OCM/ACE PERFORMED AT 2783.0 ACFT HRS AT FTCKY BY ACE TEAM MEMBER 'C' AVSCOM OCMSEC ST. LOUIS, MO. (RH7244)	B CO 7/101 AVN REGT, FTCKY	15-Nov-1989	1	QC000000
UNGROUNDING REQUIREMENTS FOR CH47D C/W I/A/W SOF MSG CH-47-89-13 TB 55-1520-240-20-41 AT 2783.1 ACFT HRS. (RH7244)	B CO 7/101 AVN REGT, FTCKY	17-Nov-1989	1	QC000000
DEGREASING OF C-BOX COOLER FAN DRIVE SHAFT C/W I/A/W SOF CH-47-89-10 TB55-1520-240-20-39 AT 2783.0 AFCT HRS. (RH7244)	B CO 7/101 AVN REGT, FTCKY	17-Nov-1989	2	QC000000
EXTENSION AND CLARIFICATION OF C-BOX COOLING FAN DRIVE SHAFT REGREASE C/W I/A/W SOF MSG CH-47-89-14 TB 55-1520-240-20-42 AT 2801.7 ACFT HRS. (RH7244)	B CO 7/101 AVN REGT, FTCKY	06-Dec-1989	1	QC000000
EXTENSION OF C-BOX COOLING FAN D/S INSP AND FINITE LIFE INCREASE OF OIL COOLER FAN (SUNSTRAND) P/N 145DS18-5: 2822.7 ACFT HRS. (RH7244)	B CO 7/101 AVN REGT, FTCKY	20-Dec-1989	1	QC000000
UNGROUNDING REQUIREMENTS C/W I/A/W SOF MSG CH-47-90-01 TB 55-1520-240-20-43 AT 2848.4 ACFT HRS. (RH7244)	B CO 7/101 AVN REGT, FTCKY	13-Jan-1990	1	QC000000



1. AIRCRAFT MODEL <b>CH-47D</b>	2. NOMENCLATURE <b>HELICOPTER, CARGO</b>	3. AIRCRAFT SERIAL NUMBER <b>8424183</b>		
REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID
RECURRING INSPECTION OF ENGINE CROSS SHAFT EDDY CURRENT C/W I/A/W SOF MSG CH-47-90-02 TB 55-1520-240-20-44 AT 2859.3 ACFT HRS. (RH7244)	B CO 7/101 AVN REGT, FTCKY	29-Jan-1990	1	QC000000
SOF MSG CH-47-90-03 TB 55-1520-240-20-42 EXTENSION OF C-BOX COOLING FAN DRIVE SHAFT REGREASE C/W AT 2859.3 ACFT HRS. (RH7244)	B CO 7/101 AVN REGT, FTCKY	30-Jan-1990	1	QC000000
EXTENSION OF VIBRATION TEST ON C-BOX COOLING FANS C/W I/A/W SOF MSG CH-47-90-05 AT 2938.2 ACFT HRS. (RH7244)	B CO 7/101 AVN REGT, FTCKY	09-Apr-1990	1	QC000000
SOF MSG CH-47-90-07 TB 55-1520-240-20-48 ONE TIME INSPECTION OF FWD XMSN MOUNT BARREL NUTS C/W AT 2939.7 ACFT HRS. (RH7244)	B CO 7/101 AVN REGT, FTCKY	20-Apr-1990	1	QC000000
SOF MSG CH-47-90-06 TB 55-1520-240-20-46 ONE TIME AND RECURRING INSPECTION OF AFT XMSN OIL COOLER FAN AT 2939.7 ACFT HRS. (RH7244)	B CO 7/101 AVN REGT, FTCKY	02-May-1990	1	QC000000
SOF MSG CH-47-90-04 CARGO HOOK/WINCH CONTROL RELEASE BUTTON GUARD. (RH7244)	B CO 7/101 AVN REGT, FTCKY	03-May-1990	1	QC000000
PHASE #1 CYCLE #1 COMPLETED AT 2939.7 ACFT HRS. NEXT PHASE DUE IS PHASE #2 CYCLE #2 AT 3139.7 ACFT HRS. (RH7244)	B CO 7/101 AVN REGT, FTCKY	18-May-1990	1	QC000000
SOF MSG CH-47-90-10 TB 55-1520-240-20-45 ONE TIME AND RECURRING INSPECTION OF RIGHT HAND AFT BELLCRANK. SUPPORT STRUCTURE DOES NOT APPLY TO THIS ACFT. (RH7244)	B CO 7/101 AVN REGT, FTCKY	22-May-1990	1	QC000000
SOF MSG CH-47-90-11 TB 55-1520-241-20-53 ONE TIME INSPECTION OF FUEL PUMP ELECTRICAL GROUND FOR CH47C/D AND REVISION TO FUEL SYSTEM EMERGENCY PROCEDURES FOR ALL CH47C/D ACFT C/W THIS DATE. (RH7244)	B CO 7/101 AVN REGT, FTCKY	07-Aug-1990	1	QC000000
SOF MSG CH-47-90-12 ONE TIME INSPECTION OF HYDRAULIC PRESSURE LIVE CLAMP MOUNTING FLATS FOR JACKS. C/W AT 3046.6 ACFT HRS. (RH7244)	B CO 7/101 AVN REGT, FTCKY	21-Sep-1990	1	QC000000

1. AIRCRAFT MODEL <b>CH-47D</b>	2. NOMENCLATURE <b>HELICOPTER, CARGO</b>	3. AIRCRAFT SERIAL NUMBER <b>8424183</b>		
REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID
ONE TIME INSPECTION OF CH47D FWD XMSNS CONTAINING SUSPECT ROTOR SHAFTS. C/W I/A/W SOF MSG CH-47-90-13 TB 55-1520-240-20-30 AT 3056.3 ACFT HRS. (RH7244)	B CO 7/101 AVN REGT, FTCKY	27-Sep-1990	1	QC000000
REPLACEMENT ENGINE EMERGENCY TIMER PANEL S/N NN316 INSTALLED INDICATING 2 MINUTES ON THE #1 ENG AND 26 MINUTES ON THE #2 ENGINE. (RH7244)	B CO 7/101 AVN REGT, FTCKY	13-Oct-1990	1	QC000000
CH-47-91-ASAM-01 TB 55-1520-240-20-51 INITIAL AND RECURRING INSP OF AFT XMSN COOLER FAN VIBRATION ANALYSIS ENTERED AT 3061.0 ACFT HRS. (RH7244)	B CO 7/101 AVN REGT, FTCKY	03-Nov-1990	1	QC000000
ONE TIME AND RECURRING INSPECTION OF PITCH LINK RETAINING HARDWARE C/W I/A/W SOF MSG CH-47-90-09 TB 55-1520-241-20-52 AT 2940.8 ACFT HRS (NOT PREVIOUSLY NOTED).	B CO 7/101 AVN REGT, FTCKY	04-Nov-1990	1	QC000000
FECF-PHL-CH-47-D056R2 FIELD RETROFIT OF DROOP STOP ASSY INCORPORATED BY BOEING REP AT 3236.3 ACFT HRS, FTCKY	B CO 7/101 AVN REGT, FTCKY	23-Jan-1991	1	QC000000
CH-47-91-ASAM-02 INSPECTION FOR COMPLIANCE OF MWO 55-1520-240-50-43 C/W AT 3114.6 ACFT HRS.	B CO 7/101 AVN REGT, FTCKY	19-Feb-1991	1	QC000000
REVISION OF CHECKLIST FOR CH47D ACFT INVOLVED IN OPERATION DESERT STORM C/W I/A/W CH-47-91-ASAM-03 AT 3155.1 ACFT HRS	B CO 7/101 AVN REGT, FTCKY	12-Mar-1991	1	QC000000
COMBAT PHASE #2 COMPLETED AT 3158.8 ACFT HRS	B CO 7/101 AVN REGT, FTCKY	29-Mar-1991	1	QC000000
SOF CH-47-91-01 TB 55-1520-240-20-55 ONE TIME INSPECTION AND REMOVAL OF COMBINING XMSN AND ENGINE XMSN CONTAINING SUSPECT PINION AND GEARS C/W. (RH7244)	B CO 7/101 AVN REGT, FTCKY	29-May-1991	1	QC000000
ACFT DEPLOYED TO AND OPERATED IN SAUDI ARABIA FROM 3046.1 ACFT HRS TO 3175.4 ACFT HRS	B CO 7/101 AVN REGT, FTCKY	29-May-1991	2	QC000000
CALCULATION OF FATIGUE LIFE COMPONENTS FOR ACFT OPERATING ABOVE 50,000 LBS GROSS WEIGHT C/W I/A/W CH-47-91-ASAM-05 TB 55-1520-240-20-56 AT 3175.4 ACFT HRS.	B CO 7/101 AVN REGT, FTCKY	29-May-1991	3	QC000000

1. AIRCRAFT MODEL <b>CH-47D</b>	2. NOMENCLATURE <b>HELICOPTER, CARGO</b>	3. AIRCRAFT SERIAL NUMBER <b>8424183</b>		
REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID
CH-47-91-ASAM-06 TB -55-1520-240-20-55 INSURE INSTALLATION OF NEW FWD XMSN OIL COOLER INLET DUCT P/N 145S1981-2,2,4 C/W AT 3175.4 ACFT HRS. (RH7244)	B CO 7/101 AVN REGT, FTCKY	07-Jun-1991	1	QC000000
CH-47-91-02 TB 55-1520-240-20-55 UPDATE TO CH-47-91-01 TO IDENTIFY SERVICEABLE COMBINING XMSN AND ENGINE XMSN C/W 3175.4 ACFT HRS. (RH7244)	B CO 7/101 AVN REGT, FTCKY	10-Jun-1991	1	QC000000
OCM/ACE PERFORMED AT 3175.0 ACFT HRS AT FTCKY BY ACE TEAM MEMBER "K" AVSCOM OCM SEC ST. LOUIS, MO. (RH7244)	B CO 7/101 AVN REGT, FTCKY	12-Aug-1991	1	QC000000
ONE TIME AND RECURRING INSPECTION OF FWD AND AFT XMSN SUPPORT STRUCTURE CH-47-ASAM-08 TB 55-1520-240-20-58 C/W 12-OCT-1991. (RH7244)	B CO 7/101 AVN REGT, FTCKY	17-Oct-1991	1	QC000000
ONE TIME INSPECTION OF INTERFERENCE BETWEEN ENGINE CROSS SHAFT AND THE RIGHT HAND FAIRING ACCESS COVER CH-47-92-ASAM-01 TB 1-1520-240-20-59 C/W 8-OCT-1991 AT 3218.0 ACFT HRS. (RH7244)	B CO 7/101 AVN REGT, FTCKY	28-Oct-1991	1	QC000000
INSTALLATION OF ONE PIECE DRIVE SHAFT AT 3183.0 ACFT HRS. (RH7244)	OLR DYNACORP, FTCKY	31-Oct-1991	1	QC000000
RESCINDING OF AIRWORTHINESS RELEASE ON INTERNAL FUEL TANK ASSEMBLIES I/A/W CH-47-92-ASAM-03 ENTERED AT 3227.1 ACFT HRS. (RH7244)	B CO 7/101 AVN REGT, FTCKY	02-Dec-1991	1	QC000000
ONE TIME INSPECTION OF GENERATOR WIRE HARNESS FOR CHAFFING C/W I/A/W CH-47-92-ASAM-02 TB 1-1520-240-20-60 AT 3229.8 ACFT HRS. (RH7244)	B CO 7/101 AVN REGT, FTCKY	04-Dec-1991	1	QC000000
MODIFICATION FOR REPLACEMENT OF COATED PITCH LINK BOLTS AT 3250.0 ACFT HRS. (RH7244)	OLR DYNACORP, FTCKY	17-Apr-1992	1	QC000000
ONE TIME TORQUE CHECK AND RECURRING VISUAL INSPECTION OF ENGINE DRIVE SHAFT LUGS AND ADAPTER LUGS C/W I/A/W CH-47-92-ASAM-04 AT 3250.2 ACFT HRS. (RH7244)	B CO 7/101 AVN REGT, FTCKY	24-Apr-1992	1	QC000000

1. AIRCRAFT MODEL <b>CH-47D</b>	2. NOMENCLATURE <b>HELICOPTER, CARGO</b>	3. AIRCRAFT SERIAL NUMBER <b>8424183</b>		
REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID
#1 ENGINE FWD MOUNT DYE PENETRANT INSPECTION COMPLETED AT 3250.0 ACFT HRS (NOT PREVIOUSLY ENTERED). (RH7244)	B CO 7/101 AVN REGT, FTCKY	04-Jun-1992	1	QC000000
CH-47-93-02 TB 1-1520-240-20-63 CHANGE OF PILOT ACTUATOR VALVE SCREWS C/W AT 3343.4 ACFT HRS. (RH7244)	B CO 7/101 AVN REGT, FTCKY	02-Nov-1992	1	QC000000
OCM/ACE PERFORMED AT 3342.0 ACFT HRS AT FTCKY BY ACE TEAM MEMBER "ADAM" AVSCOM OCMSEC ST. LOUIS,MO. (RH7244)	B CO 7/101 AVN REGT, FTCKY	23-Nov-1992	1	QC000000
CH-47-93-ASAM-02 TB 1-1520-240-20-64 INSPECTION OF ALL CH47D ACFT HI-LOC FASTENERS AT STA 83 TO STA 120 AND RESCINDING CH-47-92-ASAM-05 AND RELATED WAIVERS C/W AT 3358.6 ACFT HRS. (RH7244)	OLR DYNCORP, FTCKY	09-Mar-1993	1	QC000000
#2 ENGINE FWD MOUNT DYE PENETRANT INSPECTION COMPLETED AT 3358.6 ACFT HRS. (RH7244)	OLR DYNCORP, FTCKY	11-Mar-1993	1	QC000000
CH-47-93-ASAM-03 ALL CH47D ACFT: ONE TIME INSPECTION OF PUMPING UNIT HYDRAULIC NSN 1650-01-240-4341 C/W 17-MAR-1993 AT 3358.6 ACFT HRS. (RH7244)	OLR DYNCORP, FTCKY	17-Mar-1993	1	QC000000
TB 1-1520-200-20-30 DESERT STORM ACFT REDEPLOYMENT CLEANING REQUIREMENT C/W DURING PHASE 1-4 STIR: TB 1-1520-240-30-01. (RH7244)	OLR SYNCORP, FTCKY	14-Jun-1993	1	QC000000
PHASE 1-4 AND STIR TB 1-1500-240-30-01 COMPLETED AT 3358.6 ACFT HRS. (RH7244)	OLR DYNCORP, FTCKY	14-Jun-1993	2	QC000000
AT 3358.6 ACFT HRS #1 ENGINE EMERGENCY POWER TIMER READING WAS 2.5 MINUTES; #1 ENGINE WAS NOT REPLACED DURING PHASE 1-4 STIR. (RH7244)	OLR DYNCORP, FTCKY	08-Jul-1993	1	QC000000
AT 3358.6 ACFT HRS #2 ENGINE EMERGENCY POWER TIMER READING WAS 26.5 MINUTES: #2 ENGINE WAS REPLACED DURING PHASE. (RH7244)	OLR DYNCORP, FTCKY	08-Jul-1993	2	QC000000

1. AIRCRAFT MODEL <b>CH-47D</b>	2. NOMENCLATURE <b>HELICOPTER, CARGO</b>	3. AIRCRAFT SERIAL NUMBER <b>8424183</b>		
REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID
SOF MSG CH-47-93-03 TB 1-1520-240-20-66 ONE TIME RECORDS CHECK OF ENGINE XMSN P/N 145D6300 SERIES C/W 16-JUL-1993 AT 3367.7 ACFT HRS. (RH7244)	B CO 7/101 AVN REGT, FTCKY	20-Jul-1993	1	QC000000
OCM/ACE PERFORMED AT 3436.0 ACFT HRS AT FTCKY BY ACE TEAM MEMBER "N" AVSCOM OCMSEC ST. LOUIS, MO. (RH7244)	B CO 7/101 AVN REGT, FTCKY	15-Dec-1993	1	QC000000
CH-47-94-ASAM-05 TB 1-1520-240-20-71 ONE TIME INSPECTION OF 5000 LB TIE DOWN RECEPTICLE ASSY: C/W 3473.9 ACFT HRS. (RH7244)	B CO 7/101 AVN REGT, FTCKY	05-May-1994	1	QC000000
CH-47-94-ASAM-06 TB 1-1520-240-20-70 ONE TIME AND RECURRING INSPECTION OF PUMPING UNIT HYD C/W AT 3473.9 ACFT HRS. (RH7244)	B CO 7/101 AVN REGT, FTCKY	05-May-1994	2	QC000000
ERROR	B CO 7/101 AVN REGT, FTCKY	05-May-1994	3	QC000000
ERROR	OLR DYNCORP, FTCKY	07-Nov-1994	1	QC000000
PHASE #1 COMPLETED AT 3556.1 ACFT HRS. (RH7244)	OLR DYNCORP, FTCKY	07-Nov-1994	2	QC000000
SOF MSG CH-47-95-01 TB 1-1520-243-20-02 ONE TIME VISUAL INSPECTION OF UPPER ACTURATOR SERIAL NUMBERS DUE PRIOR TO NEXT FLIGHT. C/W AT 3556.1 ACFT HRS. (RH7244)	OLR DYNCORP, FTCKY	06-Dec-1994	1	QC000000
CH-47-95-ASAM-01 TB 1-520-243-20-01 ONE TIME AND RECURRING DAILY INSPECTION OF THE THRUST IDLER ASSY: C/W AT 4717.3 ACFT HRS. (RH7244)	OLR DYNCORP, FTCKY	20-Dec-1994	1	QC000000
CH-47-95-ASAM-02 TB 1-1520-243-20-04 ONE TIME TORQUE VERIFICATION OF THE NUTS SECURING THE #1 AND #2 PTU MOTOR/PUMPS P/N 145HS140-8: C/W AT 3581.7 ACFT HRS. (RH7244)	B CO 7/101 AVN REGT, FTCKY	23-Jan-1995	1	QC000000
OCM/ACE PERFORMED AT FTCKY AT 3601.0 ACFT HRS BY TEAM MEMBER "W". (RH7244)	OLR DYNCORP, FTCKY	03-Feb-1995	1	QC000000

1. AIRCRAFT MODEL <b>CH-47D</b>	2. NOMENCLATURE <b>HELICOPTER, CARGO</b>	3. AIRCRAFT SERIAL NUMBER <b>8424183</b>		
REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID
CH-47-95-ASAM-04 TB 1-1520-240-20-75 ONE TIME INSPECTION FOR STRATOPOWER PUMPS NSN 1650-01-249-4341 AND REPORTING FOR TURNAROUND PROGRAM: C/W AT 3640.1 ACFT HRS. (RH7244)	B CO 7/101 AVN REGT, FTCKY	30-Mar-1995	1	QC000000
SOF MSG CH-47-95-02 TB 1-1520-240-20-76 ONE TIME VISUAL INSPECTION AND TORQUE CHECK OF LOWER DRIVE LINK TO SWASHPLATE RETAINING HARDWARE: C/W AT 3670.1 ACFT HRS. (RH7244)	B CO 7/101 AVN REGT, FTCKY	06-May-1995	1	QC000000
CH-47-95-ASAM-05 TB 1-1520-240-20-77 LUBRICATION AND INSPECTION OF THE FLIGHT CONTROL ROD END BEARINGS: C/W 3758.1 ACFT HRS AND EVERY PHASE #3. (RH7244)	B CO 7/101 AVN REGT, FTCKY	06-Jun-1995	1	QC000000
CH-47-95-ASAM-06 TB 1-1520-240-20-77 REVISION TO THE INSPECTION AND LUBRICATION OF THE FLIGHT CONTROL ROD END BEARINGS: C/W 3756.1 ACFT HRS AND EVERY PHASE #1 AND #3. (RH7244)	B CO 7/101 AVN REGT, FTCKY	24-Aug-1995	1	QC000000
CH-47-95-ASAM-07 ONE TIME RECORDS CHECK AND RECURRING VISUAL INSPECTION OF ROTOR HEADS: C/W AT 3729.2 ACFT HRS. (RH7244)	B CO 7/101 AVN REGT, FTCKY	07-Sep-1995	1	QC000000
CH-47-95-ASAM-08 VISUAL INSPECTION AFT VERTICAL SHAFT AT THE TOP OF THE SLIDER: C/W AT 3731.6 ACFT HRS. RECURRING INSPECTION EACH PHASE. (RH7244)	B CO 7/101 AVN REGT, FTCKY	14-Sep-1995	1	QC000000
PHASE #2 COMPLETED AT 3754.9 ACFT HRS. (RH7244)	B CO 7/101 AVN REGT, FTCKY	02-Nov-1995	1	QC000000
CH-47-96-ASAM-01 ONE TIME INSPECTION OF ALL AFT LANDING GEAR DRAG LINK FOR NUMBER "3" OR "5" PAINTED OR MARKED ON THE LINK: C/W AT 37543.9 ACFT HRS. (RH7244)	B CO 7/101 AVN REGT, FTCKY	07-Nov-1995	1	QC000000
ACE/AACE PERFORMED AT 3804.0 ACFT HRS. (RH7244)	AVSCOM OCMSEC, FTCKY	30-Jan-1996	1	QC000000
CH-47-96-ASAM-03 ONE TIME VISUAL INSPECTION OF PRESSURE GUAGES FOR IDENTIFICATION TAPE LOCATION; C/W 3804.2 ACFT HRS. (RH7244)6	B CO 7/101 AVN REGT, FTCKY	31-Jan-1996	1	QC000000

1. AIRCRAFT MODEL <b>CH-47D</b>	2. NOMENCLATURE <b>HELICOPTER, CARGO</b>	3. AIRCRAFT SERIAL NUMBER <b>8424183</b>		
REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID
CH-47-96-ASAM-04 ONE TIME INSPECTION OF FWD ACTUATOR BOLTS P/N 114R3650-3, WITH WORD "ACCURATE" ETCHED ON THE HEAD OF BOLTS: C/W 3874.9 ACFT HRS. (RH7244)	B CO 7/101 AVN REGT, FTCKY	07-Jun-1996	1	QC000000
CH-47-96-ASAM-05 INSPECT AND REPLACE FWD ACTUATOR BOLTS P/N 114R3650-3, WITH WORD "ACCURATE" ETCHED ON HEAD OF BOLT: C/W 3874.9 ACFT HRS. (RH7244)	B CO 7/101 AVN REGT, FTCKY	25-Jun-1996	1	QC000000
CH-47-96-ASAM-06 ONE TIME RECORDS CHECK AND VISUAL INSPECTION FOR CCAD OVERHAULED ACTUATORS AND PULL TEST OF SWASHPLATES. (RH7244)	B CO 7/101 AVN REGT, FTCKY	02-Jul-1996	1	QC000000
CH-47-96-ASAM-07 VISUAL INSPECTION OF ENGINE FOD SCREEN RETAINING STRAPS FOR UNBONDING OF RUBBER STRIP: TO BE C/W N/L.T 24-JUL-1996. (RH7244)	B CO 7/101 AVN REGT, FTCKY	11-Jul-1996	1	QC000000
ACE/AACE PERFORMED AT 3891.0 ACFT HRS. (RH7244)	B CO 7/101 AVN REGT, FTCKY	05-Aug-1996	1	QC000000
CH-47-96-ASAM-08 ONE TIME INSPECTION FOR CERTAIN SERIAL NUMBERED 145DS102-3 FWD XMSN LUBRICATION PUMPS. (RH7244)	B CO 7/101 AVN REGT, FTCKY	26-Aug-1996	1	QC000000
CH-47-96-ASAM-09 INSPECTION AND REPAIR OF AFT PYLON CLAMSHELL DOOR LATCH TO PRECLUDE WEAR AND OR IN FLIGHT LOSS OF DOOR. (RH7244)	B CO 7/101 AVN REGT, FTCKY	16-Sep-1996	1	QC000000
CH-47-97-ASAM-01 TB 1-1520-240-20-90 ONE TIME INSPECTION FOR CERTAIN SERIAL NUMBERS, FWD DRIVE SHAFT ASSY. (RH7244)	B CO 7/101 AVN REGT, FTCKY	21-Oct-1996	1	QC000000
SOF MSG CH-47-97-01 ONE TIME VISUAL INSPECTION OF CH47D FWD XMSN MOUNT BARREL NUTS: C/W 18-NOV-1996 AT 3954.8 ACFT HRS. (RH7244)	A CO 8/101 AVN REGT, FTCKY	18-Nov-1996	1	QC000000
CH-47-97-ASAM-02 ONE TIME VISUAL INSPECTION OF HOIST OPEN GRIP FOR INSTALLATION OF GUARD AROUND CARGO HOOK RELEASE SWITCH: C/W 06-JAN-1997 AT 3954.8 ACFT HRS. (RH7244)	A CO 8/101 AVN REGT, FTCKY	06-Jan-1997	1	QC000000

1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO	3. AIRCRAFT SERIAL NUMBER 8424183		
REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID
PHASE #3 COMPLETED AT 3954.8 ACFT HRS: NEXT PHASE DUE: #4 AT 4154.8 ACFT HRS. (RH7244)	A CO 8/101 AVN REGT, FTCKY	10-Feb-1997	1	QC000000
CH-47-97-ASAM-03 ONE TIME AND RECURRING INSPECTION OF CABIN FLOOR AND RAMP 5000 LB TIEDOWN FITTING P/N 114S2893-6/13: C/W 11-FEB-1997 AT 3955.8 ACFT HRS. (RH7244)	A CO 8/101 AVN REGT, FTCKY	11-Feb-1997	1	QC000000
#1 AND #2 FWD MOUNTS EDDY CURRENT INSPECTION COMPLETED AT 3954.8 ACFT HRS. NOT PREVIOUSLY ENTERED BY S. COOK TI. (RH7244)	A CO 8/101 AVN REGT, FTCKY	26-Feb-1997	1	QC000000
CH-47-97-ASAM-04 ONE TIME VISUAL INSPECTION AND REPLACEMENT OF P/N 4C3074 CRISSAIR VALVES: C/W AT 3988.2 ACFT HRS. (RH7244)	B CO 7/101 AVN REGT, FTCKY	15-Mar-1997	1	QC000000
CH-47-97-ASAM-05 ONE TIME VISUAL INSPECTION AND REPLACEMENT OF P/N A04320-12 GREER NUTS WITH "G" LOGO ON DAMPERS AND DRIVEARMS: C/W AT 3988.2 ACFT HRS. (RH7244)	B CO 7/101 AVN REGT, FTCKY	15-Mar-1997	2	QC000000
CH-47-97-ASAM-06 INFORMATIONAL UPDATE POSSIBLE SOLUTION FOR NAVSTAR AN/ASN 149 (V) GPS CONTROL DISPLAY LOCKUP WHENEVER THE RECEIVER IS TRACKING SATELLITE PRN30: C/W AT 4001.1 ACFT HRS. (RH7244)	B CO 7/101 AVN REGT, FTCKY	14-Apr-1997	1	QC000000
CH-47-97-ASAM-07 ACFT ONE TIME AND RECURRING INSPECTION OF POWER DISTRIBUTION FEEDER WIRING FOR FRAYING/CHAFFING AND ARCHING/BURING: CIRCUIT BREAKERS FOR WATER INTRUSION, INDUCED CORROSION OR ARCHING AND BURNING, AND INSTALLATION OF CIRCUIT BREAKER (CB) COVERS/SEALS: C/W AT 4001.1 ACFT HRS. (RH7244)	B CO 7/101 AVN REGT, FTCKY	16-Apr-1997	1	QC000000
CH-47-97-ASAM-08 NOTIFICATION OF INSPECTION AND LUBE OF THE FLIGHT CONTROL ROD END BEARINGS IN THE FLIGHT CONTROL CLOSET AREA AT NEXT PHASE INSPECTION. RECURRING REQUIREMENT FOR PHASE #1 AND #3. (RH7244)	B CO 7/101 AVN REGT, FTCKY	28-Apr-1997	1	QC000000



1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO	3. AIRCRAFT SERIAL NUMBER 8424183			
REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID	
CH-47-97-ASAM-09 ALL CH47D, MH-47D AND MH-47E ACFT: OPERATION OF T-62T-2B APU/REPORT OF APU FLIGHT HOURS. C/W AT 4007.7 ACFT HRS. (RH7244)	B CO 7/101 AVN REGT, FTCKY	03-Jun-1997	1	QC000000	
CH-47-98-ASAM-02 EXTENSION FOR REPLACEMENT OF THE DRAG LINK ASSEMBLIES THAT ARE SUSCEPTIBLE TO STRESS CORROSION/ CRACKING TO 30-APR-1999: C/W AT 4045.5 ACFT HRS. (RH7244)	B CO 7/101 AVN REGT, FTCKY	26-Oct-1997	1	QC000000	
LATE ENTRY CH-47-97-ASAM-10 ONE TIME INSPECTION OF ANVIS/HUB POWER SUPPLY: C/W AT 4045.5 ACFT HRS. (RH7244)	B CO 7/101 AVN REGT, FTCKY	27-Oct-1997	1	QC000000	
LATE ENTRY CH-47-98-ASAM-01 INSPECTION OF CURRENT AND SIX MONTH FILE ENTRIES FOR UNCOMMANDED CONTROL INPUTS: C/W AT 4045.5 ACFT (RH7244)	B CO 7/101 AVN REGT, FTCKY	27-Oct-1997	2	QC000000	
ACFT HISTORICAL FORMS AND RECORDS CONVERTED TO ULLS-A. (RH7244)	B CO 7/101 AVN REGT, FTCKY	19-Feb-1998	1	QC000000	
SOF MSG CH-47-98-01 TB 1-1520-240-20-103 ONE TIME INSPECTION OF AFT UPPER BOOST ACTUATORS TO STATIONARY SWASHPLATE RETAINING HARDWARE: C/W AT 4110.2 ACFT HRS. (RH7244)	B CO 7/101 AVN REGT, FTCKY	18-Mar-1998	1	QC000000	
CH-47-98-ASAM-03 TB 1-2835-205-20-03 ALL CH47D/MH47E ACFT. MANDATORY TORQUE CHECK AND REMOVAL OF AUXILIARY POWER UNIT BOLTS. (CR2215)	B CO 7/101 AVN REGT, FTCKY	30-Apr-1998	1	QC000000	
CH-47-98-ASAM-04 ONE TIME INSPECTION FOR AFT XMSN WITH SUSPECTED IMPROPERLY SHIMMED INPUT PINION GEAR ASSEMBLY. (YB0591)	B CO 7/101 AVN REGT, FTCKY	19-May-1998	1	QC000000	
PHASE INSPECTION #4 COMPLETED AT 4142.0 ACFT HRS. PHASE #1 DUE AT 4342.0 ACFT HRS. (JS3718)	OLR DYNCORP, FTCKY	13-Jul-1998	1	QC000000	
SOF MSG CH-47-98-02 FLIGHT LIMITATIONS AND MAINTENANCE INSPECTIONS FOR ACFT WITH MWO 1-1520-50-67 APPLIED: NON METALIC SPLINE ADAPTERS FOR COMBING XMSN COOLING FAN DRIVE SHAFT. (JS3718)	OLR DYNCORP, FTCKY	16-Jul-1998	1	QC000000	
TCM/ACE PERFORMED AT 4147.0 ACFT HRS BY TEAM MEMBER "BB" AMCOM. (XX0000)	OLR DYNCORP, FTCKY	24-Jul-1998	1	QC000000	

1. AIRCRAFT MODEL <b>CH-47D</b>	2. NOMENCLATURE <b>HELICOPTER, CARGO</b>	3. AIRCRAFT SERIAL NUMBER <b>8424183</b>			
REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID	
CH-47-98-ASAM-05 REVISION OF CH-47-98-ASAM-02 ACFT RESTRICTED TO FLIGHT OPERATIONS AND INSPECTION PROCEDURES I/A/W CH-47-98-ASAM-05: C/W AT 4153.6 ACFT HRS. (RH7244)	B CO 7/101 AVN REGT, FTCKY	22-Sep-1998	1	QC000000	
CH-47-99-ASAM-01 ONE TIME INSPECTION OF ROTOR BLADE LAG DAMPNER OUTBOARD ROD END: C/W AT 4301.7 ACFT HRS. (RH7244)	B CO 7/101 AVN REGT, FTCKY	25-Feb-1999	1	QC000000	
CH-47-99-ASAM-02 ACTIONS TO REDUCE SUSCEPTIBILITY TO FLIGHT CONTROL LOCK-UP AND/OR UNCOMMANDED MANEUVERS: C/W AT 4307.0 ACFT HRS. (DM1816)	B CO 7/101 AVN REGT, FTCKY	02-Mar-1999	1	QC000000	
CH-47-99-ASAM-03 ONE TIME AND RECURRING INSPECTION OF HOIST/CARGO HOOK CONTROL PANEL AND WATER INTRUSION IN THE COCKPIT: C/W AT 4703.0 ACFT HRS. (RH7244)	B CO 7/101 AVN REGT, FTCKY	11-Mar-1999	1	QC000000	
CH-47-99-ASAM-04 INSPECTION OF FWD AND AFT LCT YOKE BUSHINGS AND MAINTENANCE MANUAL CHANGES: C/W AT 316.5 ACFT HRS. (RH7244)	B CO 7/101 AVN REGT, FTCKY	22-Mar-1999	1	QC000000	
CH-47-99-ASAM-05 EXTENSION FOR REPLACEMENT OF THE AFT LANDING GEAR DRAG LINK ASSEMBLIES THAT ARE SUSCEPTIBLE TO STRESS CORROSION CRACKING FROM 30-APR-1999 TO 30-OCT-2000: C/W AT 4334.6 ACFT HRS. (CS0006)	B CO 7/101 AVN REGT, FTCKY	26-Apr-1999	1	QC000000	
PHASE INSPECTION #1 COMPLETED AT 4334.6 ACFT HRS. NEXT PHASE INSPECTION: PHASE #2 DUE AT 4534.6 ACFT HRS. (DM1816)	B CO 7/101 AVN REGT, FTCKY	14-Jun-1999	1	QC000000	
SOF MSG CH-47-99-01 ONE TIME INSPECTION OF SYNC SHAFT MOUNTING BRACKETS FOR PROPER CLEARANCE TO SYNC SHAFT: C/W AT 4345.0 ACFT HRS. (RH7244)	B CO 7/101 AVN REGT, FTCKY	15-Jul-1999	1	QC000000	
SOF MSG CH-47-99-02 EMERGENCY/ IMMEDIATE GROUNDING OF ALL CH47 SERIES ACFT: 4363.9 ACFT HRS. (CS0006)	B CO 7/101 AVN REGT, FTCKY	09-Aug-1999	1	QC000000	
AIRCRAFT PLACED IN FLYABLE STORAGE I/A/W SOF MSG EMERGENCY CH-47-99-02: 4363.9 ACFT HRS. (CS0006)	B CO 7/101 AVN REGT, FTCKY	09-Aug-1999	2	QC000000	

1. AIRCRAFT MODEL <b>CH-47D</b>	2. NOMENCLATURE <b>HELICOPTER, CARGO</b>	3. AIRCRAFT SERIAL NUMBER <b>8424183</b>		
REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID
SOF MSG CH-47-99-03 INSPECTION OF CH47D ACFT FWD AND AFT XMSN GEAR AND BEARING ASSEMBLY FOR "MG" SERIAL NUMBER SUFFIX. (MR9593)	B CO 7/101 AVN REGT, FTCKY	26-Aug-1999	1	QC000000
SOF CH-47-99-04 INSPECTION OF CH47D ACFT FWD AND AFT XMSN FOR GEAR/ BEARING ASSEMBLIES IDENTIFIED BY SN PREFIX "VB" 4363.9 ACFT HRS. (JD1362)	B CO 7/101 AVN REGT, FTCKY	27-Aug-1999	1	QC000000
ACFT REMOVED FROM FLYABLE STORAGE I/A/W SOF MSG CH-47-99-04: 4363.9 ACFT HRS. (JD1362)	B CO 7/101 AVN REGT, FTCKY	27-Aug-1999	2	QC000000
SOF MSG CH-47-99-05 ALL CH47D SERIES ACFT: REPLACEMENT OF SUSPECT FWD AND AFT XMSN ASSY WITH ONES THAT HAVE BEEN INSPECTED AND CLEARED FOR OPERATION: 4380.8 ACFT HRS. (CS00006)	B CO 7/101 AVN REGT, FTCKY	13-Sep-1999	1	QC000000
OCM/ACE PERFORMED AT 4392.0 ACFT HRS BY TEAM MEMBER "BB": AMCOM/ PROJECT OLR. (TM7612)	B CO 7/101 AVN REGT, FTCKY	23-Sep-1999	1	QC000000
SOF MSG CH-47-99-03 INSPECTION OF CH47D ACFT FWD AND AFT XMSN GEAR AND BEARING ASSEMBLY FOR "MG" SERIAL NUMBER SUFFIX. (MR9593)	B CO 7/101 AVN REGT, FTCKY	26-Sep-1999	1	QC000000
SOF MSG CH-47-00-01 OPERATIONAL RESTRICTIONS AND REVISION TO HISTORICAL RECORDS FOR APU: C/W AT 4392.4 ACFT HRS. (RH7244)	B CO 7/101 AVN REGT, FTCKY	14-Oct-1999	1	QC000000
SOF MSG CH-47-00-02 REVISION TO SOF MSG CH-47-00-01 OPERATIONAL RESTRICTIONS AND REVISION TO HISTORICAL RECORDS: C/W AT 4406.1 ACFT HRS. (RH7244)	B CO 7/101 AVN REGT, FTCKY	08-Nov-1999	1	QC000000
SOF MSG CH-47-00-03 INSPECTION AND CORRECTION PROCEDURES REQUIRED I/A/W CH-47-00-03: C/W 4420.8 ACFT HRS. (MR9593)	B CO 7/101 AVN REGT, FTCKY	07-Dec-1999	1	QC000000
SOF MSG CH-47-00-04 INSPECTION OF ACFT RECORDS FOR SUSPECT ENGINE XMSN: C/W AT 4432.9 ACFT HRS. (JJ2717)	B CO 7/101 AVN REGT, FTCKY	28-Jan-2000	1	QC000000
TUNNEL CONTROL IDLER AT STA 241 UPPER STRUCTURE MOUNT BUSHING OVERSIZED .015" I/A/W TM 15-1520-240-23-11 TASK 11-16 (NF6858)	OLR DYNACORP, FTCKY	12-Apr-2000	1	QC000000

1. AIRCRAFT MODEL <b>CH-47D</b>	2. NOMENCLATURE <b>HELICOPTER, CARGO</b>	3. AIRCRAFT SERIAL NUMBER <b>8424183</b>			
REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID	
PHASE INSPECTION #2 COMPLETED AT 4532.0 ACFT HRS. NEXT PHASE INSPECTION #3: DUE AT 4732.0 ACFT HRS. (NF6858)	OLR DYNCORP, FTCKY	14-Apr-2000	1	QC000000	
CH-47-00-ASAM-01 INSPECT FUEL PODS I/A/W TB 1-1520-240-20-119: C/W AT 4535.5 ACFT HRS. (MR9593)	B CO 7/101 AVN REGT, FTCKY	28-Apr-2000	1	QC000000	
SOF MSG CH-47-00-05 TECHNICAL CH47D, MH47D AND MH47E ACFT: ONE TIME INSPECTION OF PITCH HOUSINGS: C/W AT 4535.5 ACFT HRS. (CS0006)	B CO 7/101 AVN REGT, FTCKY	02-May-2000	1	QC000000	
CH-47-00-ASAM-02 ONE TIME INSPECTION AND RECURRING INSPECTION OF ROTARY WING HHP BOLT FOR SECURITY AND SPECIFIC P/N: C.W AT 4535.5 ACFT HRS. (HM5767)	B CO 7/101 AVN REGT, FTCKY	10-May-2000	1	QC000000	
SOF MSG CH-47-00-06 APU RESTRICTION REMOVED: C/W AT 4543.5 ACFT HRS. (MR9593)	B CO 7/101 AVN REGT, FTCKY	19-May-2000	1	QC000000	
CH-47-00-ASAM-03 INITIATION OF 50 HR HYD SAMPLES: C/W AT 4543.5 CFT HRS. (ST0737)	B CO 7/101 AVN REGT, FTCKY	02-Jun-2000	1	QC000000	
CH-47-00-ASAM-04 INSPECT ROTOR HEAD DA FORM 2408-16'S FOR HHP SN PREFIX "UW": C/W AT 4565.4 ACFT HRS. (CS0006)	B CO 7/101 AVN REGT, FTCKY	27-Jul-2000	1	QC000000	
CH-47-00-ASAM-05 INSPECT FWD AND AFT SLIDER SHAFT SEALS FOR PROPER DESIGN: C/W 4565.4 ACFT HRS. (CS0006)	B CO 7/101 AVN REGT, FTCKY	27-Jul-2000	2	QC000000	
CH-47-00-ASAM-06 ONE TIME INSP OF DEFECTIVE FADEC P3 DRAIN CARTRIDGE. ALL H-47 SERIES ACFT. C/W @ 4607.0 ACFT HRS (DO0267)	B CO 7/101 AVN REGT, FTCKY 42223	21-Sep-2000	1	QC000000	
SOF CH-47-00-07, ALL H-47 SERIES ACFT, COMBINING TRANSMISSION COOLING FAN DRIVE SHAFT INSPECTIONS, I/A/W SOF CH-47-00-07 AND TB 1-1520-240-20-129. C/W @ 4607.0 ACFT HRS. (MR9593)	B CO 7/101 AVN REGT, FTCKY 42223	27-Sep-2000	1	QC000000	
CH-47-00-ASAM-07, ALL H-47 SERIES ACFT, INSPECTION OF UNTESTED FLIGHT SAFETY PART, (FSP) BOLTS, P/N 114R3650-7 I/A/W CH-47-00-ASAM-07 AND TB 1-1520-240-20-125, C/W @ 4607.0 ACFT HRS. (MR9593)	B CO 7/101 AVN REGT, FTCKY 42223	27-Sep-2000	2	QC000000	

1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO	3. AIRCRAFT SERIAL NUMBER 8424183			
REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID	
CH-47-00-ASAM-08, ALL H-47 SERIES ACFT, INSPECTION OF THE FORWARD YOKE SHAFT P/N 145C3051-1 FOR CORROSION C/W @ 4607.0 ACFT HRS. (MR9593)	B CO 7/101 AVN REGT, FTCKY 42223	28-Sep-2000	1	QC000000	
OCM/ACE PERFORMED AT 4616 ACFT HRS, BY TEAM MEMBER D, AMCOM ,PROJECT OLR FTCKY. (MA0000)	B CO 7/101 AVN REGT, FTCKY	02-Oct-2000	1	QC000000	
CH-47-01-ASAM-01 (TB 1-1520-240-20-127) ALL H-47 SERIES ACFT, INSPECT FOR INSTALLATION OF MA-16 INERTIA REELS P/N 015-870145-3-16 I/A/W CH-47-01-ASAM-01 AND TB 1-1520-240-20-127 C/W @ 4627.4 ACFT HRS. (CS0006)	B CO 7/101 AVN REGT, FTCKY 42223	13-Oct-2000	1	QC000000	
CH-47-01-ASAM-02 (TB 1-1520-240-20-130), ALL H-47 SERIES ACFT, INSPECT FOR UNTESTED FLIGHT SAFTEY PART (FSP) BOLTS, P/N 114R3650-6 AND 114R3650-11. C/W @ 4627.9 ACFT HRS. (JD1382)	B CO 7/101 AVN REGT, FTCKY 42223	20-Oct-2000	1	QC000000	
CH-47-01-ASAM-03 (TB 1-1520-240-20-131) INITIAL VISUAL, RECURRING VISUAL, AND EDDY CURRENT INSP . OF CERTAIN P/N FWD AND AFT ROTOR HUBS I/A/W CH-47-01-ASAM-03 AND TB 1-1520-240-20-131 C/W @ 4631.2 ACFT HRS. (CS0006)	B CO 7/101 AVN REGT, FTCKY 42223	09-Nov-2000	1	QC000000	
CH-47-01-ASAM-05 (TB1-1520-240-20-132) IMSP FWD AND AFT DROOP STOP BOLTS FOR PROPER LENGTH C/W 4700.2 ACFT HRS (CS0006)	B CO 7/101 AVN REGT, FTCKY 42223	21-Dec-2000	1	QC000000	
SOF CH-47-01-01 ONE TIME INSP OF AFT ROTOR HEAD ASSY'S AND ENG CROSS SHAFT ADAPTER ASSY'S C/W @ 4700.2 ACFT HRS. (JD1382)	B CO 7/101 AVN REGT, FTCKY 42223	27-Dec-2000	1	QC000000	
SOF CH-47-01-02 (TB 1-1520-240-20-136) ALL H-47 SERIES ACFT, INSPECTION OF DROOP STOPS C/W @ 4716.9 ACFT HRS (CS0006)	B CO 7/101 AVN REGT, FTCKY 42223	05-Feb-2001	1	QC000000	
LATE ENTRY - #2 ENG FWD MOUNT NDI COMP. @ 4731. NEXT DUE AT 5331.0 ACFT HRS (GM3275)	DYNCORP, FTCKY 42223	20-Feb-2001	1	QC000000	
SOF CH-47-01-03 ALL H-47 SERIES ACFT UNGROUNDING REQ. FOR ACFT WITH INCORRECTLY INSTALLED DROOP STOPS C/W @ 4731.0 ACFT HRS (JD1382)	B CO 7/101 AVN REGT, FTCKY 42223	21-Feb-2001	1	QC000000	

1. AIRCRAFT MODEL <b>CH-47D</b>	2. NOMENCLATURE <b>HELICOPTER, CARGO</b>	3. AIRCRAFT SERIAL NUMBER <b>8424183</b>			
REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID	
CH-47-01-ASAM-04 (TB 1-1520-240-20-133) ALL H-47 SERIES ACFT, INSP FOR UNTESTED FSP PART NO. 114R2168-3 AND 114R2168-4 TIE BAR PINS C/W @ 4731.0 ACFT HRS (GM3275)	DYNCORP, FTCKY 42223	23-Feb-2001	1	QC000000	
CH-47-01-ASAM-06 (TB 1-1520-240-20-133) REVISION TO CH-47-01-ASAM-04 C/W @ 4731.0 ACFT HRS (GM3275)	DYNCORP, FTCKY 42223	23-Feb-2001	2	QC000000	
CH-47-01-ASAM-07 (TB 1-1520-240-20-135) ALL H-47 SERIES ACFT, INSP FOR UNTESTED FSP BOLTS, P/N 114R3650-13 AND 114R3650-15 C/W @ 4731.0 ACFT HRS (GM3275)	DYNCORP, FTCKY 42223	23-Feb-2001	3	QC000000	
MWO 1-1520-240-50-83, FULL AUTHORITY DIGITAL ENGINE CONTROLS COMPLIED WITH, OPERATE IAW AWR FOR FLIGHT OPERATIONS ON ARMY CH-47D HELICOPTERS WITH T55-GA-714A ENGINES INSTALLED DATED 21MAR01 REV 4 COMP. AT 4731.0 ACFT HRS (VH0368)	PROJECT OLR DYNCORP, FTCKY 42223	17-Apr-2001	1	QC000000	
#1 ENG FWD MOUNT REPLACED BY CCAD FIELD TEAM @ 4731.0 ACFT HRS (GM3275)	DYNCORP, FTCKY 42223	01-Jun-2001	1	QC000000	
HASE #3 COMPLETED AT 4731.0 ACFT HRS NEXT DUE PHASE #4 4931.0 ACFT HRS (GM3275)	DYNCORP, FTCKY 42223	22-Jun-2001	1	QC000000	
WINCH CABLE GUIDE EXTENSION REPAIRED IAW LETTER DATED 20JUN01 FROM BRIAN P. NEWTON AMCOM LAR (JS3718)	DYNCORP CH-47 PHASE, FTCKY 42223	27-Jun-2001	1	QC000000	
CH-47-01-ASAM-08 ONE TIME INSP OF ALL H-47 POWER, PRESSURE, AND RETURN CONTROL MODULES TO ENSURE PROPER INSTALLATION OF SHUT-OFF DIAPHRAGM HARDWARE C/W @ 4803 ACFT HRS (TB1119)	B CO 7/101 AVN REGT, FTCKY 42223	17-Aug-2001	1	QC000000	
EMC TEST FOR 160150-10A APU COMPLETED IAW AWR DATED 09 FEB 00, @ 4811.9 ACFT HRS. (HM5767)	B CO 7/101 AVN REGT, FTCKY 42223	01-Oct-2001	1	QC000000	
CH-47-01-ASAM-09 (TB 1-1520-240-20-139) INSPECT FOR UNTESTED FSP 114R3650-9 AND BACB30ST10-40 BOLTS. C/W @ 4812.4 ACFT HRS. (HM5767)	B CO 7/101 AVN REGT, FTCKY 42223	02-Oct-2001	1	QC000000	
CH-47-02-ASAM-01 (TB 1-1520-240-20-142) ALL H-47 SERIES ACFT, ONE TIME INSP OF THE TUNNEL COVER STRUT ASSEMBLIES C/W @ ____ ACFT HRS (CS0006)	B CO 7/101 AVN REGT, FTCKY 42223	10-Oct-2001	1	QC000000	

1. AIRCRAFT MODEL <b>CH-47D</b>	2. NOMENCLATURE <b>HELICOPTER, CARGO</b>	3. AIRCRAFT SERIAL NUMBER <b>8424183</b>		
REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID
CH-47-02-ASAM-02 (TB 1-1520-240-143) FWD YOKE SHAFT REPLACEMENT DATE EXTENSION C/W 4849.6 ACFT HRS. (MR9593)	B CO 7/101 AVN REGT, FTCKY 42223	27-Dec-2001	1	QC000000
OCM/ACE PERFORMED @ 4853.0 ACFT HRS. BY TEAM MEMBER "R" AMCOM PROJECT OLR (TS0568)	DYNCORP PROJECT OLR, FTCKY 42223	10-Jan-2002	1	QC000000
SOF CH-47-02-01 (TB 1-1520-240-20-144) ONE TIME INSP OF SWASHPLATE LOWER SEAL SELF LOCKING NUTS I/A/W SOF CH-47-02-01 AND TB 1-1520-240-20-144 C/W @ 4863.3 ACFT HRS (HM5767)	B CO 7/101 AVN REGT, FTCKY 42223	25-Jan-2002	1	QC000000
SOF CH-47-02-02 (TB 1-1520-240-20-141) ALL H-47 SERIES INSP OF ROTARY WING HEAD TIE BAR ASSY AND ROTOR TACHOMEITER I/A/W SOF CH-47-02-02 AND TB 1-1520-240-20-141 C/W @ 4863.3 ACFT HRS (HM5767)	B CO 7/101 AVN REGT, FTCKY 42223	25-Jan-2002	2	QC000000
SOF CH-47-02-03 (TB 1-1520-240-20-141) ALL H-47 SERIES ACFT, INSPECTION OF THE ROTARY WING HEAD TIEBAR ASSEMBLY AND ROTOR TACHOMETER I/A/W SOF CH-47-02-03 (TB 1-1520-240-20-141) (SUPERCEEDS SOF CH-47-02-02) C/W @ 4863.3 ACFT HRS. (HM5767)	B CO 7/101 AVN REGT, FTCKY 42223	28-Jan-2002	1	QC000000
SOF CH-47-02-04 (TB 1-1520-240-20-145) ALL H-47 SERIES ACFT, INSPECTION OF THE FORWARD PIVOTING ACTUATOR TO SWASHPLATE ATTACHMENT HARDWARE FOR PROPER INSTALLATION. C/W 4867.0 ACFT HRS. (CS0006)	B CO 7/101 AVN REGT, FTCKY 42223	07-Feb-2002	1	QC000000
PHASE #4 COMP @ 4920.3 ACFT HRS., PHASE #1 DUE @ 5120.3 ACFT HRS. (MR9593)	B CO 7/101 AVN REGT FTCKY, FTCKY 42223	24-Apr-2002	1	QC000000
DRAFT MWO 1-1520-240-55-12 (CMDS) INSTALLED. OPERATION I/A/W AWR FOR CMDS DATED 06JUN02 COMPLETED @ 4931.7 A/C HRS. (MB4441)	AMCOM PROJECT OLR DYNCORP, FTCKY 42223	07-Jun-2002	1	QC000000
CH-47-02-ASAM-03 (TB 1-1520-240-20-147) INSPECT FUEL CONTROL RELAY BOX IAW CH-47-02-ASAM-03 (TB 1-1520-240-20-147) WITHIN THE NEXT 10 FLIGHT HOURS, BUT NLT 26 JUNE 2002 (BM8686)	B CO 7/101 AVN REGT FTCKY, FTCKY 42223	14-Jun-2002	1	QC000000

1. AIRCRAFT MODEL <b>CH-47D</b>	2. NOMENCLATURE <b>HELICOPTER, CARGO</b>	3. AIRCRAFT SERIAL NUMBER <b>8424183</b>			
REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID	
CH-47-02-ASAM-04 (TB 1-1520-240-20-149) ALL H-47 SERIES ACFT, INSPECT AFT YOKE SUPPORT SHAFT. C/W @ 4934.8 ACFT HRS. (DM6764)	A CO 7/101 AVN REGT, FTCKY 42223	25-Jul-2002	1	QC000000	
OCM/ACE PERFORMED AT 4960 A/C HRS BY TEAM MEMBER J AMCOM/OLR FTCKY (FS6922)	A CO 7/101 AVN REGT, FTCKY 42223	30-Oct-2002	1	QC000000	
GEN-03-ASAM-01 INSP SINGARS BATTERY BOX RIVETS C/W @ 4962.2 ACFT HRS (AD4129)	A CO 7/101 AVN REGT, FTCKY 42223	30-Dec-2002	1	QC000000	
DRAFT CH-47D INSTALLATION OF BLUE FORCE TRACKING I/A/W ENCLOSED AWR DATED 27 DEC 02 AT 4967.4 ACFT HR. (WM7649)	DYNCORP OLR, FTCKY 42223	06-Jan-2003	1	QC000000	
PHASED MAINTENANCE 400 INSP COMPLETED @ 5120.3 ACFT HRS PHASED MAINTENANCE 400 HR INSP DUE @ 5520.3 ACFT HRS I/A/W AWR DATED 02 JUNE 2003 (BB0038)	TASK FORCE 1109TH AVCRAD, CAMP ARIFJAN, KUWAIT	05-Aug-2003	1	QC000000	
CH-47-04-ASAM-01 INSPECTION OF AFT FUSELAGE BELLCRANK FASTNERS FOR CORRECT BOLT ORIENTATION C/W 5244.3 ACFT HRS (CK3489)	A CO 7/101 AVN REGT, FTCKY 42223	16-Feb-2004	1	QC000000	
OCM/ACE PERFORMED AT 5244 ACFT, HRS BY TEAM MEMBER R AMCOM PROJECT OLR (TS0568)	DYNCORP, FT. CAMPBELL, KY 42223	31-Mar-2004	1	QC000000	
CH-47-04-ASAM-02 TRANSIENT AND AVOID BANDS ON THE CRUISE GUIDE INDICATOR C/W 5244.3 ACFT HRS. (JM5967)	A CO 7/101 AVN REGT, FTCKY 42223	10-May-2004	1	QC000000	
#1 ENG FWD INBOARD MOUNT INBOARD LUG THICKNESS REDUCED TO .550. HOLE DIAMETER INCREASED TO .836 (HK5804)	DYNCORP, FT. CAMPBELL, KY 42223	23-Jul-2004	1	QC000000	
CH-47-05-ASAM-01 AFT CRITICAL DYNAMIC COMPONENTS C/W 5252.8 ACFT HRS. (KJ4862)	DYNCORP, FTCKY 42223	14-Oct-2004	1	QC000000	
CO-PILOTS PEDAL BOX LOWER YAW BELLCRANK BUSHING BUSHING HOLE OVERSIZED TOO. 449" BUSHING OD IS 0.448 MERA#FC 0386 (KJ4862)	DYNCORP, FTCKY 42223	19-Oct-2004	1	QC000000	
#2 FWD ENG MOUNT, O/B LUG PAIR, O/B LUG HOLE DIAMETER INCREASED TO 0.992", PER MEC# F34254A (KJ4862)	DYNCORP, FTCKY 42223	16-Dec-2004	1	QC000000	



1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO	3. AIRCRAFT SERIAL NUMBER 8424183			
REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID	
PHASE 1-4 COMPLETED AT 52528 HRS. NEXT PHASE #1 DUE AT 5652.8 HRS (KT4862)	DYNCORP INTERNATIONAL, FTCKY 42223	24-Feb-2005	1	QC000000	
TB 1-1520-240-30-02 CH-47D ACFT DESERT OPERATION SPECIAL INSP AND CLEANING COMPLETED AT 5252.8 ACFT HRS (KJ4862)	DYNCORP INTERNATIONAL, FTCKY 42223	24-Feb-2005	2	QC000000	
NDI OF #1 FWD & AFT ENG MOUNTS COMPLETED AT 5252.8 ACFT HRS. NEXT DUE AT 5852.8 ACFT HRS (KJ4862)	DYNCORP INTERNATIONAL, FTCKY 42223	24-Feb-2005	3	QC000000	
NDI OF #2 FWD & AFT ENG MOUNTS COMPLETED AT 5252.8 ACFT HRS. NEXT DUE AT 5852.8 ACFT HRS. (KJ4862)	DYNCORP INTERNATIONAL, FTCKY 42223	24-Feb-2005	4	QC000000	
MWO 1-1520-240-50-92 SHORTEN LH/RH INBOARD ENGINE AIR PARTICLE SEPARTOR RAILS (EAPS) C/W @ 5264.6 ACFT HRS. (GW6833)	AMCOM PROJECT OLR DYNCORP, FTCKY 42223	08-Apr-2005	1	QC000000	
OCM/ACE PERFORMED AT 5265 ACFT HRS. BY TEAM MEMBER UU & J (LH9501)	DYNCORP PROJECT OLR, FTCKY 42223	19-Apr-2005	1	QC000000	
MWO 1-1520-240-50-88 ADVANCED HEADS UP DISPLAY AND T55-GA-714A GAS TURBINE ENGINE TORQUEMETER INDICATING SYSTEM C/W @ 5264.6 ACFT HRS. (GW6833)	AMCOM PROJECT OLR DYNCORP, FTCKY 42223	25-Apr-2005	1	QC000000	
MWO 1-1520-240-50-72 LOADMASTER RADAR ALTIMETER. C/W @ 5264.6 ACFT HRS. (GW6833)	AMCOM PROJECT OLR DYNCORP, FTCKY 42223	27-Apr-2005	1	QC000000	
MWO 1-1520-240-50-77 IMPROVED AFT PYLON WORK PLATFORM DOOR LATCHES. C/W @ 5264.6 ACFT HRS. (GW6833)	AMCOM PROJECT OLR DYNCORP, FTCKY 42223	27-Apr-2005	2	QC000000	
MWO 1-1520-240-50-82 SEALED LEAD ACID BATTERY. C/W @ 5264.6 ACFT HRS. (GW6833)	AMCOM PROJECT OLR DYNCORP, FTCKY 42223	27-Apr-2005	3	QC000000	
MWO 1-1520-240-50-BFT2 BLUE FORCE TRACKING. C/W @ 5264.6 ACFT HRS. (GW6833)	AMCOM PROJECT OLR DYNCORP, FTCKY 42223	27-Apr-2005	4	QC000000	
MWO 1-1520-240-50-91 AIRWARRIOR MICRO CLIMATE COOLING SYSTEM AND MASK BLOWER SYSTEM. C/W @ 5264.6 ACFT HRS. (GW6833)	AMCOM PROJECT OLR DYNCORP, FTCKY 42223	28-Apr-2005	1	QC000000	
MWO 1-1520-240-50-90 AN/APX-118 MODES TRANSPONDER (CXP) C/W @ 5264.6 ACFT HRS (GW6833)	AMCOM PROJECT OLR DYNCORP, FTCKY 42223	04-May-2005	1	QC000000	

1. AIRCRAFT MODEL <b>CH-47D</b>	2. NOMENCLATURE <b>HELICOPTER, CARGO</b>	3. AIRCRAFT SERIAL NUMBER <b>8424183</b>		
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID
MWO 1-1520-240-55-14 INSTALLATION OF THE COMMON MISSILE WARNING SYSTEM (CMWS) C/W @ 5264.6 ACFT HRS (GW6833)	AMCOM PROJECT OLR DYNCORP, FTCKY 42223	04-May-2005	2	QC000000
RSN LSF01381 CH-47D ELECTRONIC DATA MANAGEMENT SYSTEM WITH ETHERNET HUB (GW6833)	AMCOM PROJECT OLR DYNCORP, FTCKY 42223	14-Jun-2005	1	QC000000
CH-47-05-ASAM-03 VHP SERIAL NUMBER CHECK C/W ACFT HRS: 5323.2 (PD1100)	D-6-101ST AVN, FTCKY 42223	26-Jul-2005	1	QC000000
CH-47-05-SOF-02 ROTOR BLADE ROOT END INSP C/W ACFT HRS. 5323.2 (PD1100)	D6-101ST AVN, FTCKY 42223	26-Jul-2005	2	QC000000
AWR DATED 27 JUL 05 MYLAR TEAR OFF WIND SHIELD COVERS INSTALLED @ 5323.2 ACFT HRS (GM1598)	D 6/101 GSAB, FTCKY 42223	11-Aug-2005	1	QC000000
CH-47-05-ASAM-02 AFT ROTARY WING HEAD @ 5323.2 ACFT HRS "LATE ENTRY" (GM1598)	D 6/101 GSAB, FTCKY 42223	16-Aug-2005	1	QC000000
CH-47-05-ASAM-04 AFT TRANSMISSION RETAINER @ 5323.2 ACFT HRS "LATE ENTRY" (GM1598)	D 6/101 GSAB, FTCKY 42223	16-Aug-2005	2	QC000000
CH-47-05-ASAM-06 HYDRAULIC SYSTEM PURIFICATION INTERVAL CHANGED TO 400HRS. CHANGE (HK5804)	D 6/101 GSAB, FTCKY 42223	03-Nov-2005	1	QC000000
HYDRAULIC FILTERS WITH SYSTEM PURIFICATION. RESCIND REQUIREMENTS FOR HYDRAULIC FLUID SAMPLING "LATE ENTRY" (HK5804)	D 6/101 GSAB, FTCKY 42223	03-Nov-2005	2	QC000000
CH-47-05-ASAM-05 HYD CHECK VALVES AND FLUID PARTS @ 5323.2 ACFT HRS (GM1598)	D 6/101 GSAB, FTCKY 42223	29-Dec-2005	1	QC000000
CH-47-06-SOF-01 M24 ARMANMENT SUBSYSTEM COMPLIED WITH @ 5453.6 ACFT HRS (GM1598)	D 6/101 GSAB, TIKRIT IRAQ	18-Jan-2006	1	QC000000
200 HR PHASE INSPECTION COMPLETED @ 5452.1 ACFT HRS. (GM1598)	D 6/101 GSAB, TIKRIT IRAQ	18-Jan-2006	2	QC000000
CH-47-06-SOF-02 APU AUXILIARY POWER UNIT, P/N CHECK C/W @ 5462.0 ACFT HRS (NC4746)	D 6/101 GSAB, TIKRIT IRAQ	17-Feb-2006	1	QC000000

1. AIRCRAFT MODEL <b>CH-47D</b>	2. NOMENCLATURE <b>HELICOPTER, CARGO</b>	3. AIRCRAFT SERIAL NUMBER <b>8424183</b>			
REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID	
CH-47-06-ASAM-02 INSP M24/M240H CAM FOLLOWER C/W @ 5466.5 ACFT HRS (NC4746)	D 6/101 GSAB, TIKRIT IRAQ	02-Mar-2006	1	QC000000	
CH-47-06-SOF-03 AFT ROTOR FIBER BLADE DISTORTION C/W @ 5471.5 ACFT HRS (NC4746)	D 6/101 GSAB, TIKRIT IRAQ	08-Mar-2006	1	QC000000	
AWR FOR RELOCATION OF CABIN BUBBLE WINDOWS ON CH-47D HELICOPTERS DATED 28 NOV 03, REV 1, APPLIED TO AIRCRAFT.	D 6/101 GSAB, FOB SPIECHER, IRAQ	02-Apr-2006	1	QC000001	
CH-47-06 ASAM-03 LCT. AFT ACTUATOR C/W 5556.6 (PD1100)	D 6/101 GSAB, FOB SPIECHER, IRAQ	25-May-2006	1	QC000000	
CH-47-06-SOF-04 SUSPECT AFT ROTOR BLADES C/W @ 5594.8 ACFT HRS. (NC4746)	D 6/101 GSAB, FOB, SPEICHER, IRAQ	26-May-2006	1	QC000000	
400 HR PHASE INSP COMPLETED @ 5649.8 (FB0103)	B-CO 96 ASB, FOB SPEICHER, TIKRIT IRAQ	05-Jul-2006	1	QC000000	
CH-47-06-SOF-05 SUSPECT FWD ROTOR BLADES COMPLIED WITH @ 5668,5 ACFT HRS	D CO 6-101, FOB SPEICHER, TIKRIT IRAQ	23-Aug-2006	1	QC000000	
AIRCRAFT TRANSFERED TO B CO 2/211 GSAB, INARNG	D CO 2/135 GSAB, CAMP BUERING, KUWAIT	09-Sep-2006	1	BF846868	
CH-47-06-SOF-06 AFT CRITICAL DYNAMIC COMPONENTS COMPLIED WITH @ 5685.9 ACFT HRS	D CO 2/135 GSAB, BALAD IRAQ	18-Sep-2006	1	CM806715	
CH-47-07-SOF-01, SWASHPLATE ROTATING RING EDDY CURRENT INSPECTION (INSPECTION A190 CHANGED TO 200 HOUR INTERVALS) C/W AT 5745.2 AIRCRAFT HOURS	D CO., 2-135TH GSAB, 36TH CAB, BALAD, IRAQ	25-Oct-2006	1	LR728742	
MEC: LE-BAL014-0398 DURING THE 200 HR CSP AT 5847.9 ACFT HRS, A DRIVE SHAFT BOLT CAUGHT ON THE FWD C-BOX AND #6 D/S FLEX PACK CAUSING SLIGHT DISTORTION AROUND ONE BOLT HOLE. NDI SHOWED NO CRACKING OR TEARS. UPON REINSTALLATION CHECK FOR PROPER THREAD ENGAGEMENT AND CHECK FACE OF FLEX PACK ADJACENT TO BOLT HEAD FOR PLATE DISTORTION AND SEPERATION IAW TM 1-1520-240-23-5 TASK 6-7, CHECK AGAIN IN 20 HOURS (5867.9).	B CO 449TH ASB, BALAD, IRAQ	22-Dec-2006	1	BF846868	
200 HR CSP COMPLETED AT 5847.9 ACFT HRS	B CO 449 ASB, BALAD, IRAQ	27-Dec-2006	1	BF846868	

1. AIRCRAFT MODEL <b>CH-47D</b>	2. NOMENCLATURE <b>HELICOPTER, CARGO</b>	3. AIRCRAFT SERIAL NUMBER <b>8424183</b>		
REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID
CH-47-07-ASAM-01, ARC-220/KY-100 START-UP PROCEDURES, COMPLIED WITH AT 5874.8 AIRCRAFT HOURS	D CO., 2-135TH GSAB, LSA ANACONDA, BALAD, IRAQ	17-Jan-2007	1	LR728742
CH-47-07-SOF-02 ALL H-47 SUSPECT ROTOR BLADES COMPLIED WITH AT 5893.9 ACFT HRS.	D CO 2/135TH GSAB 36TH CAB, BALAD, IRAQ	25-Jan-2007	1	CM806715
COMPLIED WITH SOF MSG CH-47-07-SOF-02, CHECK SUSPECTED DISTORTED ROTOR BLADES @ 5893.9 ACFT HOURS	D COMPANY, 2/135TH GSAB, BALAD, IRAQ	26-Jan-2007	1	SM277372
CH-47-07-ASAM-02 RIGID CONNECTING LINKS COMPLIED WITH AT 6040.7 ACFT HRS	D CO 2/135 GSAB, BALAD, IRAQ	06-Mar-2007	1	BF846868
400 HR CSP PHASE COMPLETED AT 6047.8 ACFT HRS. NEXT 200 HRS CSP DUE AT 6247.8 ACFT HRS	VERTEX/L-3, BALAD, IRAQ	25-Mar-2007	1	BF846868
ACFT RETURNED TO HOME STATION-AASF, ST PAUL MN AT 6207.2 ACFT HRS	AASF, ST PAUL, MN	11-Oct-2007	1	BF846868
CH-47-07-SOF-03 SUSPECT ROTOR BLADES C/W @ 6207.2 ACFT HRS	AASF, ST. PAUL MN	12-Oct-2007	1	BF846868
H-47-08-AMAM-02. DOES NOT APPLY TO CH-47D AIRCRAFT.	AASF, ST. PAUL, MN. 55107	18-Mar-2008	1	BF846868
H-47-08-AMAM-03 COMPLIED WITH, (DOPPLER GPS NAVIGATION SET). SOFTWARE WAS PREVIOUSLY INSTALLED.	AASF, ST. PAUL, MN. 55107	25-Mar-2008	1	BF846868
200 HR CSP COMPLETED @ 6238.0 ACFT HRS. NEXT 400 HR CSP DUE AT 6447.8 ACFT HRS.	AASF, ST. PAUL, MN. 55107	10-Apr-2008	1	BF846868
ACE PERFORMED AT 6238.0 ACFT HRS IN ST. PAUL, MN BY TEAM MEMBERS X AND V.	OLR WEST, ST. PAUL, MN. 55107	11-Apr-2008	1	BF846868
H-47-08-SOF-01 ENGINE XMSN PINION GEAR COMPLIED WITH ON 19JUN 08 PER RECORDS CHECK	ARMY FIELD MAINTENANCE /LSI, FT. LEWIS, WA. 98433	11-Nov-2008	1	SP905754
H-47-08-ASAM-01 PITCH HORN BUSHING ON FWD & AFT HEADS COMPLIED WITH ON 11 FEB 08 PER RECORDS CHECK	ARMY FIELD MAINTENANCE/LSI, FT. LEWIS, WA. 98433	11-Nov-2008	2	SP905754
CH-47-06-ASAM-01 UPPER BOOST ACTUATORS COMPLIED WITH ON 11 JAN 06 PER RECORDS CHECK	ARMY FIELD MAINTENANCE/LSI, FT. LEWIS, WA. 98433	11-Nov-2008	3	SP905754
H-47-08-AMAM-05 AFT ROTOR HEAD PVH RETIREMENT LIFE COMPLIED WITH ON 28 AUG 08 PER RECORDS CHECK	ARMY FIELD MAINTENANCE/LSI, FT. LEWIS, WA. 98433	11-Nov-2008	4	SP905754

1. AIRCRAFT MODEL <b>CH-47D</b>	2. NOMENCLATURE <b>HELICOPTER, CARGO</b>	3. AIRCRAFT SERIAL NUMBER <b>8424183</b>		
REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID
H-47-08-AMAM-04 FWD & AFT SWASHPLATE RETAINER SPACER COMPLIED WITH ON 16 JUN 08 PER RECORDS CHECK	ARMY FIELD MAINTENANCE/LSI, FT. LEWIS, WA. 98433	11-Nov-2008	5	SP905754
H-47-08-AMAM-01 AFT XMSN SHAFT SEAL RETAINER COMPLIED WITH ON 8 FEB 08 PER RECORDS CHECK	ARMY FIELD MAINTENANCE/LSI, FT. LEWIS, WA. 98433	11-Nov-2008	6	SP905754
NDI ON # 1 ENGINE FWD AND AFT MOUNT COMPLETED AT 6371.2	ARMY FIELD MAINTENANCE/LSI, FT. LEWIS, WA.	17-Nov-2008	1	SP905754
NDI ON # 2 ENGINE FWD AND AFT MOUNTS COMPLETED AT 6371.2	ARMY FIELD MAINTENANCE/LSI, FT. LEWIS, WA. 98433	17-Nov-2008	2	SP905754
NDI ON FWD ROTOR HUB COMPLETED AT 6371.2 ACFT HRS	ARMY FIELD MAINTENANCE/ LSI, FT. LEWIS, WA. 98433	18-Nov-2008	1	SP905754
NDI ON AFT ROTOR HUB COMPLETED AT 6371.2 ACFT HRS	ARMY FIELD MAINTENANCE/LSI, FT. LEWIS, WA. 98433	18-Nov-2008	2	SP905754
1200 HRS FUEL CELL INSPECTION COMPLETED AT 6371.2 ACFT HRS.	ARMY AVIATION FIELD MAINTENANCE/LSI, FT. LEWIS, WA. 98433	01-Dec-2008	1	SP905754
ACFT ACE INSPECTION COMPLETED AT 6371.2 ACFT HRS.	ARMY FIELD MAINTENANCE/LSI, FT. LEWIS, WA. 98433	03-Dec-2008	1	SP905754
MEC# F86868 AFT LEFT SIDE TORQUE BOX COVER REPAIRED COMPLIED WITH AT 6371.2 ACFT HRS.	ARMY AVIATION FIELD MAINTENANCE/LSI, FT. LEWIS, WA. 98433	21-Jan-2009	1	SP905754
TB 1-1520-240-30-02 COMPLIED WITH AT 6371.2 ACFT HRS.	ARMY FIELD MAINTENANCE/LSI, FT. LEWIS, WA.	05-Feb-2009	1	SP905754
TB 1-2840-265-23 ON # 1 ENGINE COMPLETED AT 6371.2 ACFT HRS.	ARMY FIELD MAINTENANCE/LSI, FT. LEWIS, WA. 98433	05-Feb-2009	2	SP905754
TB 1-2840-265-23 ON # 2 ENGINE COMPLETED AT 6371.2 ACFT HRS	ARMY FIELD MAINTENANCE/ LSI, FT. LEWIS, WA. 98433	05-Feb-2009	3	SP905754
200/400 CSP COMPLETED AT 6371.2 ACFT HRS. NEXT INSP. 200 CSP DUE AT 6571.2 ACFT HRS.	ARMY FIELD MAINTENANCE/ LSI, FT. LEWIS, WA. 98433	05-Feb-2009	4	SP905754

1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO	3. AIRCRAFT SERIAL NUMBER 8424183		
REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID
TUNNEL CONTROL IDLER AT STA 241 UPPER STRUCTURE MOUNT BUSHING WAS OVERSIZED, BUT WAS NOT OVERSIZED TO .030" WHICH IS THE NEXT STEP, BUSHING MEASUREMENT: OD: .459", ID: 313", LENGTH: .249" MADE IAW IETM 1-1520-240-23.	ARMY AVIATION FIELD MAINTENANCE/ LSI, FT. LEWIS, WA. 98433	17-Feb-2009	1	SP905754
APU START MODULE ASSY. THUR VISUAL INSPECTION IS IN COMPLIANCE BY CH-47-MIM-2004-001, COMPONENT HAS NO SN: #	ARMY AVIATION FIELD MAINTENANCE/LSI, FT. LEWIS, WA. 98433	20-Feb-2009	1	SP905754
AWR FOR SEI INDUSTRIES BAMBI BUCKET DATED 10APR09 APPLIED TO ACFT. EMC CHECK OK	AASF2, ST. CLOUD, MN 56304-9793	01-May-2009	1	BF846868
ACE PERFORMED @ 6443 A/C HR AT ST CLOUD MN BY HH & E	OLR WEST, FT LEWIS WA 98439	20-Jun-2009	1	CA866418
AWR FOR INSTALL OF DGNS-P3I (AN/ASN-128D) APPLIED TO ACFT. TTS 34745A DATED 05 JAN 2007 R0. EMC CHECK COMPLETED ON ACFT 8601666.	AASF2, ST. CLOUD, MN 56304-9793	09-Jul-2009	1	BF846868
COMPLIED WITH H-47-09-AMAM-02, AFT IDLER SHAFT.	AASF #2, ST CLOUD, MN 56304, ST. CLOUD, MN 56304-9793	17-Jul-2009	1	KK824090
AWR FOR INSTALL OF EBC-406HM ELT APPLIED TO ACFT. TTS 56878A DATED 13 FEB 2009 R1. EMC CHECK COMPLETED ON ACFT 8601666.	AASF2, ST. CLOUD, MN 56304-9793	20-Aug-2009	1	BF846868
COMPLIED WITH GEN-09-AMAM-03, ULLS-A CHANGE 60	AASF #2, ST. CLOUD, MN 56304-9793	08-Sep-2009	1	KK824090
H-47-09-AMAM-03 COMPLIED WITH (HHFE) ALL EXTINGUISHERS NEED TO BE REPLACED.	AASF2, ST. CLOUD, MN 56304-9793	17-Sep-2009	1	BF846868
H-47-10-ASAM-02 COMPLIED WITH (HYD CLAMPS) AT 6544.5 ACFT HRS, INSP OK, NO RE-CLAMPING REQUIRED	AASF #2, ST. CLOUD, MN 56304-9793	22-Dec-2009	1	RW963945
H-47-10-AMAM-02 COMPLIED WITH (LCF CHANGE 60B)	AASF 2, ST. CLOUD, MN 56304-9793	31-Dec-2009	1	BF846868
COMPLIED WITH REQUIREMENTS OF GEN-10-AMAM-02 (AIRCRAFT ELECTRONIC LOGBOOK)	D CO 2/211TH GSAB, ST. CLOUD, MN 56304-9793	22-Jan-2010	1	LM821929
H-47-10-AMAM-03 COMPLIED WITH (FWD ROTOR HUB RETIREMENT LIFE REDUCTION)	AASF2, ST. CLOUD, MN 56304-9793	16-Mar-2010	1	BF846868

1. AIRCRAFT MODEL <b>CH-47D</b>	2. NOMENCLATURE <b>HELICOPTER, CARGO</b>	3. AIRCRAFT SERIAL NUMBER <b>8424183</b>		
REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID
REPLACED SPLICE ANGLE AND CAP ASSY@ STA 95.00 BL18R TO BL27 I/A/W: TTS 79401 PER SCOTT KREPPS. WORK COMPLETED ON WO# 090033 AND SRA WO# 060242. ALL WORK COMPLIED WITH INSTRUCTIONS ON OTR#: AMOTRQ41 AND MEC# F106065 @ 6560.4 A/C HRS.	MO-AVCRAD, SPRINGFIELD, MO 65803	31-Mar-2010	1	RW626133
H-47-10-AMAM-04 COMPLIED WITH (AFT SLIDER SHAFT ASSY RETIREMENT LIFE).	AASF 2, ST. CLOUD, MN 56304-9793	05-Apr-2010	1	BF846868
PERMANENT CHANGES TO CONFIGURATION AND APPLICATION OF THE AWR # TTS41283 DATED 18 NOV 09 REV 10 IN RELATION OF THE MSPU MWO 1-1520-MSPU-CH47-50-1	FT. HOOD AFMA, ST. CLOUD, MN 56304-9793	25-Jun-2010	1	ON909978
EMC CHECK COMPLETED FOR AWR# TN64589C FOR ECU INSTALLATION DTD 26-AUG-2009.	AASF #2, ST. CLOUD, MN 56304-9793	03-Aug-2010	1	BK212656
TN 81823 REV. 2 DATED 06 MAY 2010, FOR THE FLEET FIELDING OF AN/ALQ-212(V)5 ATIRCM PROVISIONS APPLIED ON THIS DATE @ 6681.8 AIRCRAFT HOURS.	FT. HOOD, AFMA, DAVENPORT, IA	26-Aug-2010	1	AP787196
WR TTS 74557C DATED 01 SEP 10 FOR VERIFICATION OF DRAFT MODIFICATION WORK ORDER (MWO) 1-1520-240-50-105, DATED 23 SEP 09, FOR INSTALLATION OF BLUE FORCE TRACKER (BFT) SYSTEM WITH SINGLE ELECTRONIC DATA MANAGER (EDM) ON CH-47D HELICOPTER, PROVISIONS ENTERED ON THIS DATE @ 6681.8 AIRCRAFT HOURS.	FT. HOOD, AFMA, DAVENPORT, IA	02-Sep-2010	1	AP787196
COMPLIED WITH H-47-10-ASAM-07 (5000 POUND TIE DOWN ADAPTER RING INSPECTION)	B CO 2/211TH GSAB, ST. CLOUD, MN 56304-9793	07-Oct-2010	1	LM821929
H-47-11-ASAM-01 C/W (ALUMINUM WASHERS)	AASF #2, ST. CLOUD, MN 56304-9793	16-Oct-2010	1	CH797883

1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO	3. AIRCRAFT SERIAL NUMBER 8424183		
REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID
"LATE ENTRY" PMS #3 (400HR CSP INSP) WAS COMPLETED WITHIN THE ALLOTTED 10 PERCENT WINDOW AT 6731.0 ACFT HOURS. NEXT SCHEDULED PMS #2 (200HR CSP INSP) IS SCHEDULED FOR 6930.5 ACFT HOURS.	D CO. 1-171, TAJI, IRAQ APO AE 09378	04-Apr-2011	1	RG546546
COMPLIED WITH ASAM H-47-11-ASAM-03 @ ACFT HOURS 6851.3	D CO 1/171 GSAB, TAJI, IRAQ APO AE 09378	05-Apr-2011	1	LM821929
AUTHORIZATION IS GRANTED TO FABRICATE PART NUMBER 145S3805 USING 7075-T6 FOR CH-47 AIRCRAFT TAIL NUMBER 84-24183 IAW TM 55-1520-240-23 AND TM 1-1500-204-23 (CLAMP) MEC # F124750	D CO 1-171 GSAB, TAJI, IRAQ APO AE 09378	11-Apr-2011	1	RG546546
COMPLIED WITH ASAM H-47-11-ASAM-04 @ 6859.4 ACFT HRS	D CO. 1-171 GSAB, TAJI, IRAQ APO AE 09378	19-Apr-2011	1	JS707699
MEC (MAINTENANCE ENGINEERING CALL) # F125862. AUTHORIZATION IS GRANTED TO PERFORM A TEMPORARY REPAIR ON THE APU MOUNT BRACKET (FWD L/H SIDE) TO REMOVE A SMALL AMOUNT OF MOVEMENT/PLAY IAW TM 1-1520-240-23&P, TM 1-1500-204-23.	171 D CO. GSAB, TAJI, IRAQ APO AE 09378	27-Apr-2011	1	RG546546
200HR PHASE INSP WAS COMPLETED @ 6899.1 ACFT HRS OUTSIDE THE AUTHORIZED WINDOW (6920.5 -6940.5 A/C HRS) +/- 10 FLT HR CYCLE PHASE MAINTENANCE REQUIREMENTS. NEXT INSP DUE IS 400HR CSP @ 7099.1 ACFT HRS.	D CO. 1/171 GSAB, TAJI, IRAQ APO AE 09378	30-May-2011	1	JS707699
#1 ENGINE FORWARD MOUNT LUGS, DRAG, LINK AFT MOUNT LINK, AND RELATED PARTS INSPECTION COMPLETED AT 6899.1 ACFT HOURS.	D CO. 1/171 GSAB, TAJI, IRAQ APO AE 09378	30-May-2011	2	JS707699
#2 ENGINE FORWARD MOUNT LUGS, DRAG, LINK AFT MOUNT LINK, AND RELATED PARTS INSPECTION COMPLETED AT 6899.1 ACFT HOURS.	D CO. 1/171 GSAB, TAJI, IRAQ APO AE 09378	30-May-2011	3	JS707699
MEC AUTHORIZATION GRANTED FOR REPAIR OF CABIN CROWN DRAIN CUP/DEFLECTOR AT STATION 210 MEC F131673	B CO 640TH ASB, TAJI, IRAQ APO AE 09378	17-Aug-2011	1	GB844622
MEC AUTHORIZATION GRANTED FOR REPAIR OF CRACK AT STATION 360 DRAIN CUP/DEFLECTOR MEC F131671	B CO 640TH ASB, TAJI, IRAQ APO AE 09378	17-Aug-2011	2	GB844622



1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO	3. AIRCRAFT SERIAL NUMBER 8424183		
REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID
AUTHORIZATION HAS BEEN GRANTED BY MEC F131694 TO REPAIR A CRACK AT STA 120 FORMER AT BL 18R AND WL 50 REPAIR IS BEING DONE BY B CO 640TH ASB SHEET METAL SHOP	B CO 640TH ASB, TAJI, IRAQ APO AE 09378	19-Aug-2011	1	GB844622
A3T INSPECTION COMPLETED AT 7069.8 ACFT HRS BY ACE TEAM MEMBER "S"	TASM-E, TAJI, IRAQ APO AE 09378	27-Aug-2011	1	WC643445
PMS3 (400HR) WAS COMPLETED BY B CO 640TH ON 17 SEPT 11 AT 7069.8 ACFT HRS, NEXT INSPECTION IS PMS2 (200HR) DUE AT 7269.8 ACFT HRS.	B CO 640TH, TAJI, IRAQ APO AE 09378	17-Sep-2011	1	JG117700
AUTHORIZATION IS GRANTED TO B 2/211TH GSAB, CAMP TAJI, IRAQ PER MEC F131694, TO REPAIR CRACK AT STA 120 FORMER AT BL 18R AND WL 50 ACFT HRS 7069.8 REPAIR WAS MADE BY B CO 640TH ASB SHEET METAL.	B CO 640TH ASB, TAJI, IRAQ APO AE 09378	22-Sep-2011	1	GB844622
COMPLIED WITH AMAM H-47-11-AMAM-04 AN/ASN-128D DOPPLER AND AVIATION MISSION PLANNING SYSTEM (AMPS) SOFTWARE UPGRADE.	D CO. 1-171 GSAB, TAJI, IRAQ APO AE 09378	23-Sep-2011	1	BF743208